

# COLNE ROBOTICS

The

Colne Robotics

A R M O R I D

Construction and Operation Manual

Published by  
COLNE ROBOTICS LIMITED  
Beaufort Road, Twickenham  
Middlesex TW1 2PQ  
England  
Telephone: 01-892 8197  
© Copyright 1981

I

N

T

R

O

D

U

C

T

I

O

N.



## Introduction

The word Robot comes from the Czechoslovak language and means simply worker. It entered the English vocabulary when a play by Karel Capek was translated in 1923 for the London stage entitled R.U.R. (Rossums Universal Robots). In the play Rossum created humanoid devices to work for him. Almost all that is left of the play is the word Robot and all that it now means to us.

The image of the robot has been created in part by science fiction writer and part by the manufacturers of industrial robots. As a result most laymen do not have a clear idea of the capability or limitations of a robot or even in some cases what exactly a robot is. The Robot Institute of America puts it like this:- "A robot is a reprogrammable, multifunctional manipulator designed to move material, parts, tools or specialised devices through variable programmed motions for the performance of a variety of tasks". In other words it is an intelligent handling device. There are of course specialised pieces of machinery which are able to handle industrial work which are not robotic. What then is the difference? The significance is in the word specialised. A robot is not a specialised piece of machinery and is in fact a part of a flexible automated production line which comes "off the shelf". The robot can be programmed and is therefore infinitely variable. That is the difference and it is a big one.

The industrial robot has been in existence for a number of decades but the development of microelectronics and microprocessors over the last couple of years is the technology that has made them cost effective. Five years ago a robot had a cost ratio of about 60% electronics and 40% mechanical content. The effect of the silicon chip revolution is that it is now 20% electronics and 80% mechanics. The drop in the total price of robots as a result of the cost ratio has been dramatic. This and the rise in wage rates has caused the increase in the usage of industrial robots.

The development of the small robotic arm was largely accidental. The decision to design this small arm came from what was intended as a survey of industrial robots. It was noticed that the micro-computer hobbyist in the USA was experimenting with medium and small robotic devices of all kinds. There was however, no educational or experimental robotic device on sale anywhere in the world that gave the capability of control and handling at a price which made the robot a good microcomputer periferal.



The design of the robot as a kit is deliberate policy of the Colne Group. It enables the person assembling the device to understand the principles of the robot, although of course the machine is also available in made up form. The main opportunity that the kit form gives to hobbyists and experimental roboticists is the possibility to modify or add to their robot. There are, even at this time of writing a number of experimental projects planned. These will obviously increase in a number of developments and to keep owners of robot arms informed of events we intend to run a newsletter.

Typical of the projects will be the fitting of sensors on the grippers. This will enable the arm to have feedback from the manipulator to give a closed loop control of the device. Another form of feedback could come from sensors such as fibre optic or electro/optic devices on the joints of the machine to sense the exact position of those joints. Variations can be made around the manipulators, the substitution of the gripper for the other kinds of handling device such as a pneumatic sucker for handling sheet or paper or an electro magnetic handler for picking up ferrous metal workpieces, are planned.

Other variations will be seen in the computer programs which will drive the machine. The basis of these programs and the intelligence that they can have are shown in the chapter on software. The variations in mechanical and electronic drives in the robot give the operator the ability to simulate many of the functions of a real industrial robot. The various projects about which we are informed will be the subject of articles in the monthly newsletter which robot arm owners can subscribe to (see details in the appendix of this manual).

We are hoping that this robot arm will serve as a helpful pilot scheme for the evaluation, economical analysis and hopefully installation of its big industrial brothers in manufacturing facilities. The factors that you will have to take into consideration are:-

- Ability of the gripper and machine to handle jobs in the factory.
- Economic factors and evaluation
- Social impact of the robot

Some consideration on the three aspects are given below.

## Handling jobs in the Factory

### Non Gripping Applications

- Cleaning
- Drilling
- Spraying
  - Paint
  - Power
- Welding
  - Arc
  - Flame Cutting
  - Spotwelding
  - Stud

### Low Precision Gripping

- Investment Moulding
- Diecasting
- Forging
- Foundry Practice
- Press Work Applications
- Plastic Moulding

### High Precision Gripping

- Interstage Tooling
- Transfer between Stations in Forging
- "        "        "        in Metal Stamping and Drawing
- Loading and Unloading Tools in General Work
- Inspection Probing
- Filament Winding
- Wire Wrapping
- Sprue Cutting
- Sorting and Packing
- Precision Drilling
- Precision Routing
- Deburring

### Advanced Assembly and Parts Control

- Palletizing
- Brick Manufacturing
- Glass Manufacturing

These applications are listed in order of difficulty for robotic handling. It would be unwise for the inexperienced to consider attempting more than those in the first two categories.



In surveying the existing use of industrial robots nearly 90% of all applications fall within the first two areas where no gripping or standard gripping surfaces are available. Such applications require low levels of precision, say plus or minus a couple of millimeters. It is in these two areas that the most cost effective applications will at this time be found until robots can be made more intelligent.

The other important parameters are weight of workpieces and speed of handling required. Light handling is generally associated with speed of operation and it is normally difficult for a robot to compete with human response in this kind of handling. The speed of robots is much more suited to handling forgings etc. but this often leads to a variable scenerio which require intelligence, and the variation of the machine by operator or computer.

It is possible for the production technician who is inexperienced in robots to identify a robot application in his own manufacturing facility. He must bear in mind that the above mentioned limitations and possibilities but a robot installation starts with the requirements of the production line. The first thing that he must look for is what skills are needed at a particular workstation, by the operative. His work must be assessed for the use of:-

- a. Sight
- b. Touch
- c. Hearing

and how often does the pattern for the use of these skills repeat or be made to repeat without variation. For the purpose of this exercise we will assume that the production engineer is looking for robotic installation opportunities in the non gripping or low precision gripping application areas.

Having looked at a,b and c he will probably discard 'c' as a factor in most operations. Therefore any workstation that needs hearing to do the job will not be a candidate for robotics. The 'a' aspect will now have to be considered from the point of view of how sight is used. It is necessary to decide if sight is used in establishing position or has it got other functions such as quality control etc? If anything other than position is involved then this application must also be discarded.

You will see that we are coming down one factor and that is position. Such a positioned workpiece must have little variability. The workpiece must be offered up to the robot at the same place (+ a small discrepancy), in the same orientation and with little or no variation in the receiving station although now it can be reorientated by other machinery if required and possibly may not need the accuracy of placement. Timing may or may not be important in this last operation but speed to integrate the working of the robot into production line is obviously important.

It will be obvious to you that we are looking at a single robot installation as a hybrid approach using both robots and workpeople on the production line. We are also looking at the possible installation of the simplest robotic device. This of course means safety considerations such as not mixing machines and people in the workspace of the robot. It does however, give a bonus which will allow the robot to work within the safety guards of a machine and could therefore speed up cycle times of the machines working.

You will see that an installation will require modifications both to the robot and to the production machinery. It may be that you need to change parameters of the production line such as workpiece flow and timing, size of batches of items, positioning of the workpiece but remember that the robot, through the computer that controls it can also be very variable to meet a production situation. The main variability of the robot being given by the programming (see the chapter on software).



### Economic Factors

The evaluation of the installation of a robot in your factory include cost versus savings and the throughput of your factory. The details of costs and savings are as follows:

#### Financial Evaluation - Robot Costs

1. Purchase price of robot.
2. Purpose made tooling. This cost may be considered as a part of the cost of the robot for your specific task and may be regarded as part of the cost of the robot.
3. Installation costs may be a constituent of the robot project or may be partially carried as a part of plant changes that were to be made in the normal programme for production machinery depreciation and replacement.
4. Maintenance can be a variable figure depending upon usage. Such costs in foundry work are usually more than in plastic moulding. There is a general rule of thumb with production equipment that maintenance costs are about 10% of the purchase price per annum on a two shift basis.
5. Operating Power is a minor cost which can be assessed in conjunction with the robotic device manufacturer.
6. Finance allows for the current cost of money or alternatively estimates the expected return on investment.
7. Depreciation of ordinary general purpose multi shift equipment is usually about 10 years on a straight line basis.

#### Robot Savings

- a. Labour displaced is the crux of robot usage although protection of workers in hazardous working conditions is a close second. It is obvious that if a robot can be made to work more than one shift the savings will be greater. This cost should also include fringe benefits and be shown as an hourly rate.
- b. Quality improvement is a considerable factor particularly if the job is repetitive to the extent of becoming intensely boring so that the task is subject to moods and attitudes of the workers. In addition there can be aspects of environment to be taken into consideration such as physically hazardous or demanding which enables robotic control to produce a better or more thorough job.



- c. Increase in throughput either from higher quality or increased output or a mixture of both gives a capability which might be mixed. If the throughput increases the workpieces available in a certain part of the production scheme could mean a modification of the installation (Robot Costs 3). This will have to be costed and set against the savings seen in this item of increased output. The improvement of utilisation of capital assets should not be ignored any may assist the benefit of one for one displacement of a worker.

These lead to a simple payback formula which would give you a timespan, say eighteen months which will be the time that the robot will take to return its investment.

Payback Formula

$$\text{Payback years} = \frac{\text{Robot Cost (1, 2 \& 3)}}{\text{Labour (a) - Robot Expense (4, 5, 6, 7)}}$$

This simple formula does not include 'b' and 'c' in the robot savings.

Example

Single Shift Operation

$$P = \frac{\text{£25,000}}{\text{£12 (250 x 8 hrs) - £1.20 (250 x 8 hrs).}}$$

P =

The capacity and throughput of your factory is an important factor in the installation of a robotic installation and must be examined.

Here are some of the questions that the robot manufacturer will ask you. You will probably find that it is not worth installing a device unless you have a throughput of two or three million workpieces a year. Production should be fairly steady and the need for the level of the production to last for some years is important to the payback calculation. Other aspects of the handling of the workpiece are more complex but the potential installer must know these answers so do your homework.

## Capacity and Throughput

### Volume of Throughput

1. Number of workpieces per annum
2. Is the volume of production steady?
3. If there is a variation can you give an indication of the throughput over 12 months.
4. Is the annual production going to last at the present level or above over the next three years.

### Workpiece Configuration

1. What is the size of the Workpiece?
2. What is the weight of the workpiece?
3. Will it deform under its own weight?
4. Will it break or crack if dropped from a height of 3 inches onto a hard surface?



### Social Impact of the Robot

This checklist enables you to evaluate the positive and negative aspects of robot acceptance in your workforce. This is quite different to factors in management acceptance and should be treated as two separate parts of the total equation in robot installation.

Each item has a positive and negative share of the total percentage of the checklist findings. The total can be treated as an indicator and the points can be modified by item and total using management action.

	<u>Total points</u>	<u>Positive</u>	<u>Negative</u>
1. Will workers be given assurance of keeping their jobs	20		
2. Can displaced workers be retained in equal rated jobs	15		
3. Will workers benefit in terms of			
Relief from Boredom	5		
Health	4		
Safety	2		
Difficult or dirty tasks	7 total	15	
4. Is present worker management climate in favour of discussing			
Economic Conditions	3		
Labour Unrest	5		
Is it usually distrustful	7 total	15	
5. Has the company enough economic strength to guarantee promises are kept	5		
6. Have management particularly in the engineering department shown ability to establish dialogue with the workers	5		
7. Is management concern for the quality of the job or is it only for the economic aspect	5		
8. Will there be a plan to upgrade workers who will supervise robotic systems	5		
9. Will workers pay rates suffer by robot breakdown etc.	5		

	<u>Total points</u>	<u>Positive</u>	<u>Negative</u>
10. Has management respected the skills and intelligence of the workforce in the past	3		
11. Will this checklist be shared with the workforce and will the result be discussed	3		
12. Will robot training be on company time and will workers be sent to a 'robot training' school.	2		
13. Can workers air their views without concern or fear of ridicule	2		
	Total	100	

Positive points

Negative points

Nett Score

Score Indicator

Probability of Acceptance

80 - 100

There is a high acceptance of the concept of robotic and automation systems being installed in your factory.

60 - 80

There is a tollerable possiblilty of acceptance of robotic and automation systems.

40 - 60

There is little possiblilty of acceptance, of robotic and automation systems unless action is taken to increase the score and therefore acceptance level.

0 - 40

Forget it.

The examination of the above aspects of robot installation and the understanding of the principles involved using the robot will give you an understanding of the factors involved in an installation of a robot. More information can be obtained from the Department of Industry, the Production Engineering Research Association and the British Robot Association all of whose addresses are shown elsewhere in this manual.



M

E

C

H

A

N

I

C

S.

## MECHANICS

### 2.1 Description

The ARMDROID consists of five main parts.

#### The base

The base performs not just its obvious function of supporting the rest of the arm. It also houses the printed circuit boards and the motor that provides the rotation.

#### The Shoulder

The shoulder, which rotates on the base by way of the main bearing, carries five motors and their reduction gears which mesh with the reduction gears on the upper arm.

#### The Upper Arm

The lower end of the upper arm carries the gears and pulleys that drive the elbow, wrist and hand. It rotates about a horizontal axis on the shoulder.

#### The Forearm

The forearm rotates about a horizontal axis on the upper arm and carries the wrist bevel gears.

#### The Wrist and Hand

The two wrist movements, the rotation about the axis of the hand ("twist") and the rotation of the hand about a horizontal axis ("up and down"), depend on a combination of two independent movements. The twist is accomplished by rotating both bevel gears in opposite directions, while the up and down movement is done by turning the gears in the same direction. Combinations of the two movements can be got by turning one bevel gear more than the other.

The three fingered hand with its rubber fingertips has a straightforward open and shut movement.



## 2.2 Technical Hints

### 1. FITTING BELTS ONTO PULLEYS

Fit belt over small pulley first and then work onto unflanged edge of large pulley a little at a time - do not attempt to get belt fully onto pulley until you have got it on by one or two millimeters all round. (Belts can be damaged if they are crimped). When fitted belts should not be drum tight there should be just a little play, or friction will rear its ugly head again.

### 2. FITTING SWITCHES

On initial fitting do up bolts only enough to hold switches in position. Finally after gears are fitted swing switches so that they clear gears by approximately one millimeter and finally tighten.

### 3. FITTING PULLEYS TO MOTORS

You will find the motor shafts have end float with a light spring action pulling the shaft in. Do not pull shaft out against this spring when fitting pulley as this will cause friction and loss of effective motorpower.

### 4. LUBRICATION

Use light oil (three in one or similar), just a drop on all parts that slide or pivot. DELRIN is a self lubricating material but the friction is a lot lower with a drop of oil. We only have limited power from the motors so we want to make the most of it so work spent on eliminating friction which will pay performance dividends. Check all bores and bearings for free running - any tightness is usually caused by burrs or stray bodies in bores. Remove burrs from Delrin with a sharp knife, from metal with a scraper.

Disposable hyperdermic is ideal for lubricating - scrounge one from your local friendly GP or Hospital.

## REED SWITCH POLICY

Micro-switches are included in the assembled and unassembled Armdroid packages as optional extras. It must be stressed, however, that the machine will function perfectly well without the micro-switches, but a check must be kept on the number of complete revolutions of the base. Any more than  $1\frac{1}{2}$  turns will put a strain on the stepping motor leads where they connect to the printed circuit boards.

To prevent any difficulty in the fitting of reed-switches after the initial assembly the magnets will be inserted during manufacture. This will save the dismantling of the Armdroid in the field. Magnets will be included in all the kits.

There will be a nominal charge of £15 for the inclusion of reed-switches in both the assembled and unassembled Armdroids.

PART NUMBERS INVOLVED: \*09\*10\*15\*16\*18/16\*18/12\*



### 2.3 TOOLS LIST INC. Lubricants etc

General and small circlip pliers

7mm spanner - supplied

5.5mm spanner - supplied

Metric steel rule, (part identification)

Hyperdermic syring or small oilcan and 3 in 1 oil

"Superglue" and if possible "Loctite"

Cold vaseline or cycle bearing grease

Tweezers

Allen keys for M3 grub screws - supplied

M4 grub screws - supplied

M4 bolts - supplied

Light weight hammer (fitting rollpins)

## 2.4 ASSEMBLY

<u>Description of item</u>	<u>Part No</u>
✓ Base	01
✓ Base Bearing support column	02
✓ Base motor	03b
✓ Base motor short pulley 20 tooth	04b
Base reduction gear spindle	05
Turned thick wide washer 16mm x 2mm	06
Reduction gear	07
Base belt (medium length) 94 teeth	08m
Base switch support 12mm x 11mm	09
Base switch	10
Shoulder pan	11
Shoulder bearing ring	12
Base gear (large internal dim)	13
Bearing adjusting ring	14
Hand motor support bracket	15
Hand motor	03h
Hand switch bracket	16
Motors - Upper arm	03u
Fore arm	03f
Wrist action	03w
Motor pulleys - Upper arm	04u
Fore arm short 14 tooth	04f
Wrist action long 20 tooth	04w
Hand short 20 tooth	04h



DESCRIPTION OF ITEM	Part No	
Shoulder Side Plates	017	
Switch support bar 107mm x M3 at ends	019	
Support bar spacers M3 clearance X	018/16	
	018/12	
Motor support bracket stiffener 107mm x M3 at ends	019	
Support Bar spacers	018/54	
	018/41	
Reduction gears	020	
Reduction gear spindle 96mm x 6mm	021	
Drive belts long = 114 teeth	08/1	Hand
medium = 94 teeth	08/m	Fore/Upper arm
short = 87 teeth	08/s	Wrist action
Upper Arm Drive Gear small internal dim no drum	021	
Upper arm side plates	022	
Upper arm brace	023	
Gears wrist action	024	
hand action	025	
fore arm	026	
Idler pulley	027	
Shoulder pivot 96mm x 8mm spindle	029	
Fore arm side plates	030	
Fore arm brace	031	
Fore arm pulley	032	

DESCRIPTION OF ITEM	Part No.
Elbow Idler pulleys hand wrist	033
Elbow spindle 65mm x 6mm	034
Wrist bevel gear carrier	035
Wrist guide pulleys	036
Wrist bevel gears (flanged)	037
Wrist pivots	038
Hand bevel gear (no flange)	039
Finger support flange	040
Hand pivot	041
Finger tip plates	041
Finger cable clamp	042
Small finger spring	043
Finger tip pivot	044
Middle finger plates	045
Middle finger pivot	046
Large finger spring	047
Finger base	048
Long finger pins 16mm x 3mm	050/1
Short finger pins 13mm x 3mm	050/s
Small finger pulleys	051
Large finger pulleys	052
Large hand sheave pulley	053
Small hand sheave pulley	054
Hand sheave pin	055
Finger tip pads	056
Base pan	057



DESCRIPTION OF ITEM	Part No.
Board Spacers	018/41/54
Spacer bars for boards	058
Rubber feet	059
Cable springs wrist action short	060
Cable springs grip, elbow long	061

PREPARATION AND FIXINGS ETC

DESCRIPTION OF ITEM	Item No.
Magnets	101
Bearing adjustment ring grub screws M4 x 8mm NB + self made plug to protect the fine bearing thread	102
Turned cable clamps 6 x 6mm M3 tapped	103
Cable clamp grub screws M3 x 4 pointed head	104/105
Crimped type cable clamps crimped eyelets	106
Gear Cable grub screws M4 x 6mm flat head	107
Bushers 8mm bore long with flange - shoulder	108
Shoulder pivot spindle spacer	108a
6mm bore short with flange - elbow	109
8mm bore long with flange - wrist	110
8mm bore no flange main gear inserts	111
Gear to sheet metal screws M3 x 6 slot hd CSK	112
Spring pillar and base switch M3 x 10 cheese head	113
Base bearing to shoulder pan M4 x 16 CSK socket head	114

DESCRIPTION ITEM	Item No.
Motor bolts, Base bearing to base M4 x 10 Elbow spindle hex hd	115
Hand to finger, hand to bevel gear M3 x 6 cheese hd	116
Shoulder spindle M5 x 10 hex hd	117
General sheet metal fixing M3 x 6 hex hd	118
M4 Nuts	119
M4 Washers	120
M4 Shakeproofs elbow spindle	121
M5 shakeproofs shoulder spindle	122
M3 Nuts	123
M3 washers - switches	124
6mm steel balls - base bearing	125
Magnetic reed switches	010
Driver board	126
Interface board	127
Edge connector	128
6mm Washers	129
Roll pins	130
4.5mm circlips	131
3mm circlips	132
Elbow spacer	133



## 2.5 ASSEMBLY

### Preparation

Study the parts list, drawings and the parts themselves until you are sure you have identified them all. Assemble the tools suggested in the list of tools (2.3). Read carefully technical hints section. Solder 12 in o ribbon cable to each motor. Glue magnets (101) into the slots in the reduction gears, noting that the hand gear (25) needs no magnet. Check that the adjusting ring 14 of the main bearing screws easily onto its base. Clean both if necessary. Insert bushes into the arms, if necessary using a vice, but taking care not to distort the sheet metal.

### Construction

Fit base bearing support (2) column inside base (1). (M4 bolts, nuts.) NB NUTS INSIDE BASE

Bolt 1 motor (shorter cable) inside base. (M4 hex bolts, washers on motor side - nuts on inside). Fit pulley to spindle base of motor with the grub screw at the top (O46). Fit base reduction gear spindle (O7) to base. (Thick turned washer, M4 hex bolt) Fit reduction gear and belt. Place a small drop pf oil on the reduction gear spindle before fitting reduction gear.

When fitting belts they should be placed fully on the motor spindle and worked gently onto the reduction gear, a small section of their width at a time. (see general hints on lubrication)

Fit base switch support. (M3 hex bolt) NB DRAWING FOR POSITION. Fit base switch and run wires through adjacent hole. (M3 x 10 cheesehead, washer)

Fit bearing ring (12) (long spigot down) through shoulder base pan (11) from inside. The base gear (13) fits on the lower face of the pan with the magnet at 2o'clock as seen from inside the pan with the flange at the top. (M4 countersunk x 16mm bolts, nuts)

(This step and the next are simpler with some help from an assistant). Put shoulder base pan (gear side up) on to 3in supports (books etc,) so that the bearing support column can be inserted. Practise this movement to make sure all is well. Smear vaseline from a fridge, or grease on the bearing track of the flange, and using tweezers to avoid melting the vaseline carefully place 24 ball bearings round the flange, embedding them into grease. There will be a slight gap when all the balls are in place. Invert the base and inser the threaded bearing support column inside the bearing ring taking care not to dislodge any of the balls so that the base pan meshes with the base gear. Keep the two parts level in the same relationship by taping the parts together with a piece of wood or a spanner 5mm thick between the motor pulley and the shoulder base pan.



Large rubber bands can be used instead of tape. An assistant to hold the parts for you will be useful here.

Turn the assembly the other way up (the base is now on the bench with the shoulder base pan above it. Put more grease round the bearing track and embed 24 more ball bearings in it. Gently lower the adjusting ring (14) on to the threaded base and then screw the finger tight, remove with tape, adjust the ring until the base pan moves freely without play then tighten the grub screw, inserting a small wood plug to protect the bearing thread. (M4 grub screws) (102). The bearing may need adjusting after some use as it beds in.

Fit hand motor bracket (15) to shoulder base pan (M3 bolts) then the hand motor O3h (M4) and the hand motor pulley. Then fit the hand reed switch bracket (M3) and the switch (M3 x 10 cheesehead bolts).

Fit motors to the shoulder side plates (17) and feed the cables through the holes towards the inside. The bolts which are next to the reduction gears should be placed nut out to prevent the reduction gears catching on the end of the bolts. Fit correct pulleys (O4u/f/w) to the motor spindles noting which pulleys from the drawing, tighten the grub screws.

Fit the shoulder plates. This is simplified by loosely tightening the end bolts to support the weight. Feed the motor cables down through the main bearing (M3).

Slide switch support (19) bar through spacers (18), switches (101) and motor support bracket (see drawing for correct order of spacers). You will need to be able to adjust the position of the reed switches after the arm is fitted so that they clear the gear wheels ie tangential to shoulder pivot. Fit the motor support stiffener bar and spacers. Leave nuts finger tight. (M3 nuts).

Assemble reduction gear support bar (21), assemble with the correct length drive belts (O8s/m/l) over each gear, reduction gears facing in correct direction and the thin metal M6 washers at either end. (see drawing) Slide gently into position and bolt in the support bolts (M4 a 10mm) Fit the belts round the motor pulleys.

Put upper arm drive gear on the outside of the upper arm side plate. The magnet should be at 1 o'clock, viewed from the gear side of the arm. (M3 CSK screws x 6mm) Fit a brace to one upper arm side piece (22), then fit the other side piece to the brace. Fit all bolts and nuts before tightening any of them. Check 8mm shoulder spindle (29) slides freely through acute bushes in upper arm side pieces and through bores of drive gears, pulleys and spacers. Assemble by sliding shaft from one side and threading gears, pulleys and spacers on in the correct order of orientation - use drawing.



Fit pulley (32) to the outside of the forearm side plate (30) (M3x6mm) (countersunk screws). Fit a brace to one forearm side plate, then fit the other side plate to the brace. Check for squareness before finally tightening bolts.

Put elbow pivot through bushes and an 8mm bar through wrist bushes. (M3 bolts, nuts) Check fit before assembly. Assemble the pulleys (33) on the elbow spindle (34), lubricate and fit it to the large arm, and bolt through into spindle. (M4 bolts, washers)

Assemble the wrist bevel gear carrier (35) and wrist pulleys (36) and then tap the roll pins gently home with a small hammer, supporting aluminium gear carrier to prevent distortion.

Fit the wrist gears on the bushes (37) from the outside. Fit bevel gear carrier (35) between the wrist bevel gears (37), line up holes in end of wrist pivot (38) bores with tapped hole in carrier by peering down pivots. If you do not have a screw gripping or magnetic driver use a little piece of masking tape or sellotape to fix M3 cheesehead screw to the end of your screwdriver in such a way that it will pull off after tightening - check gears pivot freely on pivots and that the whole assemble can pivot in oilite bushes (drops of oil on faces of gears and pivots)

Screw the finger support flange (40) to the hand bevel (39). (M3 x 6mm cheesehead screws) Screw the hand pivot (41) to the bevel gear carrier (35). Tighten on a drop of loctite if available, gently by turning a pair of pliers inside it. The bevel gears should be positioned with their grub screws pointing towards the hand when the hand and the forearm are in line (see drawing).

Assemble the fingertip (42) and cable clamp (43) with the small spring (44) on the pivot (45), and clip together with large circlips on the cable clamp. The spring should be positioned so that the "back" of the spring is on the knuckleside of the fingertip, thus tending to open the hand.

Assemble the middle finger (46) and its pivot (47) with the large spring (48). Fix to the finger base (49) with the long pin (50/L) (16mm x 3mm) and two small circlips (see drawing). Fix one circlip to the pin before one begins to assemble.

Join the fingertip to the middle section with the short pin (50/S) (13mm x 3mm) and two small circlips.

Cut off one end of the tip spring about 8mm-10mm beyond its hole. Level with its hole bend the spring through a right-angle to secure it. Repeat at the other end. Trim the inner end of the middle finger spring flush with the end of the finger end and treat the outer end as above.

Fit the small pulley (51) to the finger middle section using a short pin (13mm x 3mm) and two small circlips. Fit the larger pulley (52) to the finger base with a long pin (16mm x 3mm) and two small circlips.

Screw the finger base to the finger support flange. Make sure that the fingers are evenly spaced and do not interfere with each other, and then tighten. (M3 x 6mm cheesehead)

Assemble the large and small hand sheave pulleys using the large circlip on hand sheave pin (55).



## CABLE THREADING

Slide arm into shoulder, you will need to align the reduction pulleys between the main drive gears as you lower the arm into place, and assemble using M5 hex head bolts and shakeproof washers. Tighten and check the reduction gears "mesh" correctly and the arm moves freely.

Connect grip action cable tail to shoulder base pan via the spring correctly placed over the pulley and tension using the normal method with the cable clamp.

Glue strips of rubber to finger tips using superglue.

The driver and interface board should be bolted to the base pan using the spacer bars (58) and spacers. Bolt base pan (57) to base (M3 x 6mm hex head).

### Hints: Useful tools are:

- a) 2 or 3 'bulldog clips' to maintain the tension in the cable over completed sections of each cable while the remainder is threaded. Masking tape can also be used for this purpose.
  - b) Ends of the cable can be prevented from fraying by placing a drop of 'superglue' on the end of area where it is to be cut. The excess should be wiped off on a piece of paper.
- NB. This process also stiffens the end which is useful when threading the cable through the pulleys.
- c) Ensure all grub screws are in position but are not obstructing the cable holes. Also check there are no burrs remaining from machining blocking the holes.
  - d) The cables can be threaded before the arm is bolted for the shoulder which eases the problems of access considerably. The 'grip action' cable tail can be taped or clipped to the arm and connected and tensioned with its spring after the arm is fitted to the shoulder,
  - e) When tensioning the cable, if it is passed through the clamp and back, then connected to the spring adequate tension can be applied by pulling the 'free tail' and then nipping it with the grub screw. A frined will be useful if around, but it is quite possible without. The correct tension can be easily judged, as when completed the coils of the spring should be just separated, though this is not critical.

- f) During threading the correct 'route' can be ascertained from the expanding drawings. It is very important these should be followed exactly especially the position of the grub screws when they are tightened on the cable. If this is wrong it will effect the performanc of the arm.
- g) Care should be taken to avoid the cable kinking or crossing itself on the drums.
- h) Experienc has shown that the best order to thread the cables and lenth to use. (Excess can be trimmed easily later but makes tensioning simpler)

First	- Wrist cables one at a time	1.47m (each)
Second	- Elbow cable (set up the spring pillar first - M3 x 10mm cheesehead and 2 M3 hex full nuts) attach crimped cable clamp to forearm first using M3 x 10 chhese head and two nuts as a cable pillar	0.95m
Third	- Single finger cable (fix to the hand sheave pulley using M3 x 6mm cheesehead and crimped cable clamp	0.18m
Fourth	- Double finger cable (loop over small hand sheave pulley on grip action pulley and adjust so that G A P is even when pulleys are evenly positioned)	0.36m
Fifth	- Grip action cable (start at end fixed in cable drum and stick other end to arm while fitting it to the shoulder then tension with the spring to the shoulder base pan.	1.3 m

- i) Ends using the crimped cable eyelets should be threaded through the eyelet and a small thumb knot tied to prevent the cable slipping before crimping the bracket using crimping or ordinary pliers. So not crimp too light or you may cut through cable, though KEVLAR is very tough.

E

L

E

C

T

R

O

N

I

C

S



## INTERFACE DRIVER BOARD

ITEM	VALUE	QUANTITY
Resistors		
R1	1K0	1
R2	10K	
R3-8	2K2 resistor network	1
R9	1K8	
R10	1K8	
R11	1K8	3
R12	15K	1
R13	10K	2
R14	18ohm 5w	1
R15-R20	1K0	6
Capacitors		
C1	100p polystyrene	1
C2	1.0vf Tant	1
C3-C15	10nf ceramic	13
Semiconductors		
IC1	74LS 125	
IC2	74LS 125	2
IC3	74LS 04	1
IC4	74LS 123	1
IC5	74LS 366	1
IC6	74LS 138	1
IC7-IC12	74LS 175	6
IC13-IC16	ULN2003A	4
IC17	UA 7805	1
ZD1	BZX 13v ZENER	1
Miscellaneous		
MXJ 10 way edge connector		
5 way PCB plug and socket connector		
Through Pins		
16 pin IC sockets		
14 pin IC sockets		
4 way modified PCB plug and socket		

## GENERAL ASSEMBLY SEQUENCE FOR THE PC BOARD

- A Fit all of the through pins to the board.
- B Fit and screw the 5v regulator to the board.
- C Identify and fit the resistors and the 13v zener to the board. The black band v points to the motor connectors (on the zener DIODE).
- D Identify and fit all capacitors to the board.
- E Solder the 2k2 resistor network, IC sockets, and the 4 and 5 way PCB plugs to the board.
- G Solder the 10 way socket to the board.

### NOTE:

Refer to the overlay diagram and parts list to ensure that the resistors, capacitors, IC,s and other parts are inserted into the correct locations on the PC Board.

## BASIC BOARD CHECKS

- A Check the board for dry joints and re-solder any found.
- B Hold the board under a strong light source and check the underside to ensure there are no solder bridges between the tracks.

## FITTING THE PC BOARD TO THE BASE OF THE ROBOT


The PCB should be fitted to the base plate using the nylon pillars provided.

## MOTOR CONNECTION

Connect the motors to the 5way sockets, ensuring correct 15v polarity, via the ribbon cable, referring to the diagram provided to ensure correct connection.

## POWER CONNECTION

Connect the power to the modified 4way socket ensuring correct polarity as shown below.



Blue = Pin 1 on I/P connector=0v      15v = Brown = Pin 2 on I/P connector


### NOTE

A number of diagrams are given, explaining in detail the inter-connections between the motors and the PCB, if the motors are connected in the manner shown then the software provided will map the keys 1-6 and q,w,e,r,t,y to the motors in the following way

1, q, = GRIPPER.      2, w, = left wrist.      3, e, = right wrist.  
4, r, = forearm.      5, t, = shoulder.      6, y, = base.


as shown in the diagram, the two middle pins of the stepper motors should be connected together and to 15v.

Motor Connection And Designation Layouts




Ribbon Cable To Stepper Motor Connections

- Qa Black or Green
- Qb Red or Purple
- Qc Brown or Blue
- Qd Orange or Grey
- +15v Yellow or white



Motor Assignments To Functions

- Motor 1 = Grip
- Motor 2 = Left Wrist
- Motor 3 = Right Wrist
- Motor 4 = Elbow
- Motor 5 = Shoulder
- Motor 6 = Base





## ELECTRONICS

### 3.1 Description

#### The Interface

To enable the Armdroid to function with as wide a range of microprocessor equipment as possible, the interface is designed round a standard 8-bit bidirectional port. This may be latched or non-latched. If non-latched, the interface will normally be used to input data to the micro.

In the output mode the port is configured as follows. The eight lines are defined as four data bits (D8-D5), three address bits (D4-D2) and one bit (D1) to identify the direction of data travel on the port. Four data lines are provided so that the user can control the stepper motor coils direct from computer.

The address bits are used to channel the step pattern to the selected motor. The three address bits can define eight states, of which 1-6 are used to select one of the motors, while states 0 and 7 are unallocated.

D1 indicates the direction of data travel, to the motors when D1 is low, from the microswitches, if installed, when D1 is high. The transition of D1 from high to low generates a pulse which causes the step pattern to be latched into the addressed output latch.

In the input mode D8 - D3 are used to read the six microswitches on the arm. These reed switches and magnets provide a "zero" point for each of the movements of the arm, which can be used as reference points for resetting the arm in any position before a learning sequence begins.

D2 is spare. It is an input bit which can be buffered and used for an extra input sensor, allowing the user to connect a 'home brew' transducer to the system.

The interface circuitry consists of twelve TTL components which decode the data and route it out to the selected motor driven logic. IC1 and IC2 buffer the data out to the decoder and latches. IC6 decodes the three input address bits to provide eight select lines, six of which are for the latches IC7 - IC12.

## INTERFACE ONLY

D1 is buffered and fed into a monostable (IC4) to generate a clock pulse. This causes the decoder to provide a latch pulse for approximately 500ns to the addresses motor control latch. D1 is tied to pull-up resistor (R1) so that the line is high except when are output from the microprocessor. The buffers IC1 and IC2 are enabled by the buffered output of bit 1 so that data are fed to the latch inputs only when bit 1 is low. The bit 1 buffer is always enabled because its enable is tied low.

The microswitch inputs are buffered by IC5 which is enabled by the complemented output of bit1, so that when bit1 is high IC5 is enabled, and the contents of the microswitches will be input to the microprocessor. This allows the user to operate the arm under bit interrupt control, giving instant response to a microswitch change and avoiding having to poll the microswitches. The six microswitch inputs are pulled up; thus the switches can be connected via only one lead per switch, with the arm chassis acting as ground.

## THE MOTOR DRIVERS

the motor drivers are designed so that the arm can be driven from the output of the computer interface circuitry.

The six motor driver stages need two power supplies: 15v at about 3A and 5v at 150 MA.

The four waveforms QA-QD are then fed into IC's 13-16 which are 7 x Darlington Transistor IC's. These provide the high current needed to drive the stepper motor coils, the driving current being about 300 MA at 15v.



## CONNECTION OF THE ARMDROID TO THE TRS80 PRINTER PORT

The TRS80 printer port can be used to drive the robot arm, but when using the printer port it will not be possible to read the reed-switches connected to the arm as this port is not a bi-directional port. The TRS80 to ARMDROID connections are shown below.

### TRS80 PRINTER PORT PIN CONNECTIONS

18  
17  
15  
13  
11  
9  
7  
5  
3

### ARMDROID CONNECTION ON INTERFACE BOARD

19 blue  
0 volts red  
D8 Marron  
D7 Red  
D6 VAVANJA  
D5 AMARILLO  
D4 Verde  
D3 Azul  
D2 Moravisol  
D1 gris

The software driving the motors should output data to the robot arm in the following manner.

The following Z80 code sequence assumes the correct driving pattern and motor address is in the Z80 accumulator.

```
OR      Ø 1H      ; Set bit D1
LD      PORTAD,A; Send data to port
AND     ØFEH     ; Clear bit D1
LD      PORTAD,A; Now latch data pulse to
                        ; selected motor
```

In the case of the TRS80 level 11 the printer port address is:

PORTAD equals 37E8H

S E C T I O N 1

A S Y S T E M : E Q U A T E S

B S Y S T E M V A R I A B L E S

C S Y S T E M C O N S T A N T S



ARM TRAINER MK2AL  
DIRECT FULL STEP MOTOR CONTROL  
FOR TRS80 MODEL 1, LEVEL 11  
BY ANDREW LENNARD

\*\*\* July 1981 \*\*\*

## 4. SOFTWARE

### 4.1 Introduction

A machine code program, LEARN , to drive the ARMDROID has been specially written. It was designed for the Tandy TRS-80 Model 1 Level 11, and the loading instructions given here apply to that computer. But the program can be easily adapted to any Z80 microprocessor with the necessary port, and versions made available for the leading makes with variations of these instructions where appropriate. But of course users can write their own software in whatever language they choose.

### 4.2 Loading

When in Basic type SYSTEM, press ENTER, answer the '\*' with LEARN and then press ENTER again. The cassette tape will take about 1½ minutes to load. Answer the next '\*' with / 17408 and press ENTER.

### 4.3 General Description

LEARN is a menu-oriented program for teaching the ARMDROID a sequence of movements which it will then repeat either once or as many times as you like. The program is divided into four sections, one for learning the sequence and for fine-tuning it, one to save the sequence on tape and load it again , one for moving the arm without the learning function, and finally two exit commands.

We suggest that, if this is your first encounter with the program, you should read quickly through the commands without worrying too much about understanding all the details. Then go to Section 4.5 and follow the 'Sequence for Newcomers'. This will give you a good idea of what the program does. After that you can begin to discover some of the subtleties of planning and fine-tuning sequences of movements.

### 4.4 Explanation

#### L(EARN)

Stores a sequence of manual movements in memory. The arm is moved using the commands explained under M(ANUAL) . You can exit the command by pressing 0 (zero) , press G(O), and the arm will repeat the movement you have taught it.

On pressing L(EARN) you will be asked whether you want the S(TART) again or C(ONTINUE) from the current position. The first time press S(TART) . The arm is then free to be moved by hand without the motors' torque preventing you. Move it to a suitable starting position, then press the space bar. You will find that you cannot now move the arm by hand.



To add a sequence already in memory press C(ONTINUE) instead of S(TART).

Using the manual commands, move the arm to another position. As it goes the computer is adding up the steps each motor is making, either forward or back, and storing the data in memory. (holding the space bar down during manual control slows the movement)

Exit by pressing 0 (zero).

D (ISPLAY)

Displays the sequence stored in memory. The sequence can be edited with the E(DIT) command.

The six columns of figures correspond to the six motors, and the order is the same as that of the 1-6/Q-Y keys (see M(OVE)). The first row (RELPOS) shows the current position. Each row represents a stage of the movement, and the actual figures are the number of steps each motor is to make, positive for forward, negative for reverse. The maximum number of steps stores in a row for one motor is +127 or -128, so if a movement consists of more than this number it is accomodated on several rows.

Movements of the arm can be fine-tuned by editing (see E(DIT)) the figures on display until the arm is positioned exactly.

Scrolling of the display can be halted by pressing 0 (zero). To continue scrolling, press any other key. To display the figures one after the other, keep pressing 0.

E(DIT)

Allows the user to change the figures in the memorised sequence.

Truncate a sequence by pressing R(OW COUNT), then ENTER, then the number of the last row you want performed, and finally ENTER. This clears the memory from the next step pnwards, so you should only do this if you do not want the rest of the sequence kept in memory.

By pressing M(OTOR STEP), you can change any of the numbers in any row and column.

S(ET ARM)

Sets the current position of the arm as the 'zero' or starting position.

When pressed from the Menu, it simply zeroes the first row of the display.

S(ET ARM) has another function. During a L(EARN), pressing S(ET ARM) at any moment when the arm is at rest will ensure that the movements before and after are separated from each other instead of being merged. This is the way to make quite sure that the arm passes through a particular point during a sequence. Try the same two movements without pressing S(ET ARM), and note the difference in the display.



It is important to realise that, if a sequence has been memorised and S(ET ARM) is pressed from the Menu when the arm is not in its original starting position, pressing G(O) will take the arm through the sequence but from the new starting point. This can be useful for adjusting the whole of a sequence (perhaps slightly to right or left), but it can lead to the arm running into objects if the new starting point is not selected with care.

W(RITE)

Writes a memorised sequence to cassette tape.

R(EAD)

Reads a previously written sequence from cassette tape into memory.

C(CHECK)

Compares a sequence written to cassette tape with the same sequence still in memory, to verify the tape.

G(O)

Moves the arm through a memorised sequence, either once or repeatedly.

It is important to make sure that the starting point in memory is the right one, or the sequence may try to take the arm into impossible positions. (see S(ET ARM))

T(O START)

Takes the arm back to the zero or starting position.

F(REE)

Removes the motors torque from the arm, thus allowing it to be moved by hand.

M(ANUAL)

Gives the user control of the movements of the arm direct from the keyboard. It is used (a) for practising manual control before L(EARN)ing, (b) for trying new combinations of separate movements, and (c) for moving the arm to a new starting position before pressing S(ET ARM). Holding the space bar down slows the movement by a factor of about 3.

The motors are controlled with the keys 1-6/Q-Y. The keys operate in pairs, each pair moving a motor forwards and backwards. Any combination of the six motors may be moved together (or of course separately), but pressing both keys of a pair simply cancels any movement on that motor.

The geometry of the arm is designed to give the maximum flexibility combined with maximum practicality. A movement of one joint affects only that joint: with some designs one movement involuntarily produces movement in other joints.



It is a feature of the ARMDROID that it has a so-called 'parallelogram' operation. Starting with the upper arm vertical, the forearm horizontal and the hand pointing directly downwards, the shoulder joint can be rotated in either direction and the forearm and hand retain their orientation. Equally the forearm can be raised and lowered while leaving the hand pointing downwards. Moving the arm outwards and down by rotating both the shoulder joints together still leaves the hand vertical. This is of vital importance for simplifying the picking and placing of objects.

The motors controlled by the keys are:

1/Q: Gripper  
2/W: Wrist left  
3/E: Wrist right  
4/R: Forearm  
5/T: Shoulder  
6/Y: Base

B(OOT)

Returns the computer to the program start and clears the memories.

Q(UIT)

Returns the computer to TRS80 System level.

#### 4.5 INTRODUCTORY DEMONSTRATION SEQUENCE

1. After loading the program, the screen shows the menu. Press L to enter L(EARN).
2. Screen: START AGAIN OR C(ONTINUE) FROM PRESENT POSITION, (.) TO EXIT. Press S
3. Screen: " ARM RESET  
ARM NOW FREE TO MOVE  
TYPE SPACE BAR WHEN READY, OR FULL STOP TO EXIT"  
Now move the arm so that both arm and forearm are vertical with the hand horizontal. For coarse movements grasp the forearm or upper arm and move it. For fine adjustments and for movements of the hand, it is better to use the large white gear wheels in the shoulder joint. Press the space bar and the arm will become rigidly fixed.
4. Screen: "\*\*\* TORQUE APPLIED \*\*\*"  
You can now move the arm using the 1-6/Q-Y keys as explained in the manual section. Try just one movement alone at first. Now press O (zero) to exit from L(EARN). The arm will return to the starting position, and the Menu appears on the screen.
5. Screen: Menu. Press D for D(ISPLAY).
6. Screen: Display and Menu. The numbers of steps you applied to each motor have been memorised by the computer, and these steps are now displayed see D(ISPLAY) section for explanation. Press G for G(O).
7. Screen: "DO (F) OREVER OR (O) NCE?. Press O (letter O), and the arm will repeat the movement it has learnt.
8. Screen: "SEQUENCE COMPLETE" and Menu. Press L.
9. Screen: as 2 above. This time press C. Now you can continue the movement from this position, using the 1-6/Q-Y keys as before. Now press O (zero). Again the arm returns to its original position.
10. Screen: Menu. Press D
11. Screen: Display and menu. Your new movement has been added to your first. Press G.
12. Screen: as 7 above. This time press F. Each time a sequence is started a full point is added to the row on the screen. To stop press full point.

This is a very simple demonstration of how complex movements can be built up, learnt as a sequence and then repeated endlessly and with great accuracy.



SYSTEM EQUATES

```

PORT    EQU    04    ; ARM PORT NUMBER
FINAD   EQU    02B2  ; SYSTEM RESTART
PCHR    EQU    0033H ; SYSTEM PRINT CHARACTER
GCHR    EQU    0049H ; SYSTEM GET CHARACTER
KBD     EQU    002BH  ; SCAN KEYBOARD
PUTSTR  EQU    28A7H  ; SYSTEM PRINT STRING
CASON   EQU    0212H  ; CASSETTE ON
CASOF   EQU    01F8H  ; CASSETTE OFF
RDHDR   EQU    0296H  ; READ HEADER ON CASSETTE
READC   EQU    0235H  ; READ CHARACTER FROM CASSETTE
WRLDR   EQU    0287H  ; WRITE HEADER TO CASSETTE
WRBYA   EQU    0264H  ; WRITE CHARACTER TO CASSETTE
MINUS   EQU    '-'    ; ASCII MINUS
SPAC    EQU    ' '    ; ASCII SPACE
NL      EQU    0DH    ; ASCII NEW LINE
NUMBA   EQU    30H    ; ASCII NUMBER BASE
MAXLE   EQU    10     ; UPPER BOARD FOR ARST ROW COUNTER

;   ORG    17408    ; = 4400 TRS80 HEX ADDRESS
;                   ; FOR START OF PROGRAM

```

VARIABLES USED

MIN	DEFB 00	; Has value of one if number input negative
MAN	DEFB 00	; If MAN = zero then steps are stored
STRFG	DEFB 00	; If STRFG non zero then store TBUF array
KEYP	DEFB 00	; Set if key pressed in KEYIN Routine
FORFG	DEFE 00	; Set if sequence to be done forever
COUNT	DEFB 0000	; Number of motor slices stored
CUROW	DEFB 0000	; Pointer to next free motor slice
ARRAYS		
NUMAR	DEFS 10	; Store used for Binary to ASCII Conversion ; Routine CTBAS
POSAR	DEFS 12	; Each two bytes of this six element array ; contain on value which is used to ; keep track of each motors motion, ; hence the array can be used to reset ; the arm, moving it into a defined ; start position. ; Each 16 bit value stores a motor ; steps in two's complement arithmetic.
CTPCS	DEFS 6	; 6 Bytes, each relating to a motor. ; A number from 1-4 is stored in ; each bytes and this is used to ; index the FTABL (see constant definition)
TBUF	DEFS 6	; When learning a move sequence the ; six motors motions are stored in this ; six byte array. Each byte relates ; to a motor and holds a motor step ; count in the range -128 to +127 ; If the motor changes direction or a ; count exceeds the specified range then ; the whole TBUF array is stored in ; the ARST array and the TBUF array ; is cleared. ; TBUF means temporary buffer.
DRBUF	DEFS 6	; Each byte relates to the previous ; direction of a motor.
MOTBF	DEFS 6	; A six byte array used by DRAMT to ; tell which motors are being driven, and ; in which direction. ; Bit zero set if motor to be driven ; Bit one set if motor in reverse ; Byte zero if motor should not be driven.
ARST	DEFS N*6	; This array holds the sequence that ; the user teaches the system. The array ; consists of N*6 bytes where N is ; the number of rows needed to store the ; sequence.



## CONSTANTS USED

```
FTABL      DEFE 192      ;  
           DEFB 144      ;  
           DEFB  48      ;  
           DEFE  96      ;
```

```
;  
; FTABL is a small table which defines the  
; order of the steps as they are sent out  
; to the arr. To drive each motor the  
; DRAMT routine adds the motors offset  
; which is obtained from CTPOS and adds  
; this to the FTABL start address -1. This  
; will now enable the DRAMT routine to  
; fetch the desired element from the FTABL  
; array, and this value is then sent to  
; the motor via the output port.
```

CONSTANTS AND ARRAYS  
STRINGS

```

MK (AL2) SIGON      DEFM      *** COLNE ROBOTICS ARM CONTROLLER
          ***'

          RELYQ     DEFW      ØØØDH
          DEFB      ØDH
          DEFM      'REALLY QUIT? (Y/N)'
          DEFW      ØØ
          SIGOF     DEFW      ØDØDH
          DEFM      'YOU ARE NOW AT TRS8Ø SYSTEM LEVEL'
          DEFW      ØØ
          ECOMS     DEFM      'EDIT (M)OTOR STEP, OR (R)OW COUNT?'
          DEFW      ØØØDH
          COUTS     DEFM      'NEW UPPER ROW BOUND IS?'
          DEFB      ØØ
          EDSTR     DEFM      'ROW NUMBER?'
          DEFB      ØØ
          BADMS     DEFM      '*** BAD INPUT VALUE ***'
          DEFW      ØØØDH
          MOTNS     DEFM      'CHANGE STEPS ON WHICH MOTOR?'
          DEFB      ØØ
          NVALS     DEFM      'REPLACEMENT STEP VALUE?'
          DEFB      ØØ
          GUESS     DEFM      'LRN, READ, CHECK,WRITE, GO, DISP, BOOT, MAN,
          QUIT, SETA, TOST, EDT, FREE
          DEFW      ØØØDH
          RORNM     DEFM      'DO (F)OREVER OR (O)NCE?'
          DEFB      ØØ
          CASRD     DEFM      'TYPE SPACE BAR WHEN READY, OF FULL STOP TO EXIT'
          DEFB      ØØ
          QMESS     DEFM      'PARDON'
          DEFW      ØØØDH
          BOOTS     DEFB      ØDH
          DEFM      'WANT TO RE-START (Y/N)?'
          DEFB      ØØ
          RELNS     DEFM      'START AGAIN OR (C)ONTINUE FROM CURRENT POSITION
          (.) TO EXIT
          DEFW      ØØØDH
          DISPS     DEFB      ØDH
          DEFM      ' *** MOVEMENT ARRAY DISPLAY *** '
          DEFB      ØDH
          DEFW      ØØØDH
          NODIS     DEFM      '*** NO SEQUENCE IN STORE ***'
          DEFB      ØDH
          DEFW      ØØØDH
          OVFMS     DEFM      'NO MORE ARM STORE LEFT, DELETE OR SAVE?'
          DEFW      ØØØDH
          DONMS     DEFB      ØDH
          DEFM      'SEQUENCE COMPLETE'
          DEFW      ØØØDH
          RDMSG     DEFM      '*** READ ERROR ***'
          DEFW      ØØØDH
          TAPOK     DEFM      '*** TAPE OK ***'
          DEFW      ØØØDH
          STRET     DEFM      'ARM RESET'
          DEFW      ØØØDH
          NOTOR     DEFM      'ARM NOW FREE TO MOVE'

```



```
TORMS  DEFB  ØØØDH
        DEFB  ØDH
        DEFM  '*** TORQUE APPLIED ***'
        DEFW  ØØØDH
POSST  DEFM  'RELPOS='
        DEFB  ØØ
```

S E C T I O N 2

C

O

M

M

A

N

D

R

O

U

T

I

N

E

S



## COMMAND INDEX

STARM..... Program entry point  
LEARN..... Learn a sequence command  
EDIT..... Edit a sequence command  
READ..... Read in sequence from tape command  
WRITE..... Write sequence to tape command  
CHECK..... Check stored sequence command  
BOOT..... Re-start system command  
FINSH..... Exit from system command  
SETARM..... Set start position command  
TOSTM..... Move arm to start position command  
FREARM ..... Free all arm joints  
MANU..... Go into manual mode  
GO ..... Execute stored sequence command  
DISPLAY..... Display stored Sequence command

MAIN LOOP

; Program start

```

STARM      CALL CLRSC      ; Clear the TRS80 Screen
           LD HL,SIGON    ; Point to sign on message
           CALL PSTR      ; Print it
           CALL PNEWL     ; Print a new line
           CALL INIT      ; Set up system
QUES1      CALL DELT      ; Small delay
           LD HL,QUESS    ; Point to menue string
           CALL PSTR      ; Print it
           CALL GCHRA     ; Get response and print it
           CALL PNEWL     ; Print new line
           CP NL          ; Is response a newline
           JR Z,QUES1    ; Yes then ignore
           CP 'L'        ; Is response an 'L'
           JP Z,LEARN    ; Yes do learn section
           CP 'E'        ; Is it an 'E'
           JP Z,EDIT     ; Yes do edit
           CP 'R'        ; Is it an 'R'
           JP Z,READ     ; Yes then do read command
           CP 'W'        ; Is it a 'W'
           JP Z,WRITE    ; Yes do write command
           CP 'C'        ; Is it a 'C'
           JP Z,CHECK    ; Yes do check routine
           CP 'S'        ; Is it an 'S'
           JP Z,SETAM    ; Yes then do arm set
           CP 'T'        ; a 'T'
           JP Z,TOSTM    ; Yes then move arm to start
           CP 'G'        ; a 'G'
           JP Z,GO       ; Do execute movements stored
           CP 'D'        ; a 'D'
           JP Z,DISP     ; Yes then display ARST array
           CP 'B'        ; a 'B'
           JP Z,BOOT     ; Yes then restart system
           CP 'M'        ; an 'M'
           JP Z,MANU     ; Yes the Manual control of arm
           CP 'F'        ; a 'P'
           JP Z,FREARM   ; Yes then clear all motors
           CP 'Q'        ; a 'Q'
           JP Z,FINSH    ; Yes then quit program
           LD HL,QMESS    ; Point to 'PARDON' message
           CALL PSTR      ; Print it
           JP QUES1      ; Try for next command

```



THE LEARN ROUTINE

; This section deals with the recording  
; of an arm sequence

```

LEARN      LD      HL,RELNS ; Point to learn message
           CALL   PSTR      ; Print the message
           CALL   GCHRA     ; Get response and print it
           CALL   PNEWL     ; Print a new line
           CP     '.'       ; Response a '.'
           JP     Z,QUES1   ; Back to main loop is uder types a '.'
           CP     'S'       ; Response an 'S'
           JR     Z,WAIT1   ; Learn sequence from start
           CP     'C'       ; a 'C'
           JR     Z,NOINT   ; Continue learning from end of
                           ; sequence
           CALL   PNEWL     ; output a new line
           JR     LEARN     ; Bad answer so try again
WAIT1      CALL   MOVTO     ; Move arm to start position
           CALL   INIT      ; Clear variables
WAIT2      LD      HL,CASRD ; Point to waiting message
           CALL   PSTR      ; Print it
           CALL   GCHRA     ; Get response and print it
           CALL   PNEWL     ; Print new line character
           CP     '.'       ; Response a '.'
           JP     QUES1     ; Exit to main loop if so
           CP     SPAC      ; Is it a space?
           JR     NZ,WAIT2  ; If not then bad input, try again
           CALL   TORQUE    ; Switch motors on
           JR     STLRN     ; Do rest of learn
NOINT      LD      HL,(COUNT); Get current count
           LD      A,L      ;
           OR     H         ; Is it zero?
           JR     Z,NOSTR   ; Yes then can't add to nothing
STLRN      XOR     A        ; Clear manual flag
           LD     (MAN)A    ; Because we are in learn mode
CONLN      CALL   KEYIN    ; Drive motors and store sequence
           OR     A         ; Zero key pressed
           JR     NZ,CONLN ; No then continue
           CALL   MOVTO     ; Move arm to start position
           JP     QUES1     ; Back to main loop

```

EDIT FUNCTION

```

EDIT      LD      HL,(COUNT) ; Get row count
          LD      A,L          ;
          OR      H            ; Test for zero
          JP      Z,NOSTR     ; Yes then nothing in store
EDSRT     LD      HL,ECOMS    ; Print edit message
          CALL    PSTR        ;
          CALL    GCHRA       ; Get response
          CALL    PNEWL       ; Print a new line
          CP      'M'         ; Is response an 'M'
          JR      Z,EDMOT     ; Yes then edit motor
          CP      'R'         ; Is response an 'R'
          JR      NZ,EDSRT    ; No then try again
          LD      HL,COUITS   ; HL = New row count message
          CALL    PSTR        ; Print it
          CALL    GINT        ; Get 16 bit signed integer
          JP      NZ,BADC     ; Non zero return means bad input
          LD      A,H         ; Test top bit of HC
          BIT     7,A         ;
          JP      NZ,BADC     ; If negative then bad input
          LD      BC,(COUNT) ; Get count value
          PUSH   HL          ; Save response
          OR     A           ; Clear carry flag
          SBC   HL,BC       ; See if response < current count
          POP    HL         ; Restore response
          JR     NC,BADC     ;
          LD     (COUNT),HL ; Replace count with response
          JP     QUES1       ; Back to main loop
EDMOT     LD      HL,EDSTR    ;
          CALL    PSTR        ; Print 'row number'
          CALL    GINT        ; Get integer response
          JR     NZ,BADC     ; Bad answer
          LD     A,H         ;
          BIT    7,A         ; No negative row count
          JR     NZ,BADC     ; allowed
          LD     A,H         ;
          OR     L           ; or zero row count
          JR     Z,BADC      ;
          LD     BC,(COUNT) ; Get row count into BC
          INC   BC          ; Move count up one
          PUSH  HL          ; Clear carry flag
          SBC  HL,BC       ; Subtract count from response
          POP   HL         ; Restore response
          JR   NC,BADC     ; If greater than allowed error
EDOK      DEC   HL         ; Move response down one
          ADD   HL,HL       ; Double HL
          PUSH  HL         ; Save it
          ADD   HL,HL       ; Row count x 4
          POP   BC         ; BC = row count x 2

```



```

ADD      HL,BC      ; HL = Row count x 6
LD       BC,ARST   ; Get store start address
ADD      HL,BC      ; Add row offset
PUSH     HL         ; Save resulting pointer
LD       HL,MOTNS  ; Print
CALL     PSTR      ; Motor number string
CALL     GINT      ; Get Answer
JR       NZ,BADNM  ; Bad answer
LD       A,H       ;
OR       A         ;
JR       NZ,BADNM  ; Response too large
LD       A,L       ;
CP       1         ;
JR       C,BADUM   ; No motor number < 1
CP       7         ;
JR       NC,BADNM  ; No motor number > 6
POP      HL        ; Restore = Memory pointer
DEC      A         ; Motor offset 0 → 5
LD       C,A       ;
LD       B,0       ; Add to memory pointer
ADD      HL,BC     ; Now we point to motor in store
PUSH     HL        ; Save pointer
LD       HL,NVALS  ;
CALL     PSTR      ; Print new step value
CALL     GINT      ; Get response
JR       NZ,BADNM  ; Bad answer
LD       A,H       ;
CP       0FFH     ;
JR       NZ,PEDIT  ; We have a positive response
BIT      7,L       ; New negative step value too
JR       Z,BADNM   ; large
JR       MOTAS     ; Step value OK
PEDIT    OR       A ; New positive step value too
JR       NZ,BADNM  ; large
BIT      7,L       ; so exit
JR       NZ,BADNM  ; else ok
MOTAS    LD       A,L ; Get step value
POP      HL        ; Restore memory pointer
LD       (HL),A    ; Place step value in store
JP       QUES1     ; Go do next operation
BADNM    POP      HL ;
BADC     LD       HL,BADMS ; Print error message and
CALL     PSTR      ;
JP       QUES1     ; return to main loop

```

READ ROUTINE

; Reads stored sequence from cassette  
 ; into memory

```

READ  LD      HL,CASRD  ; Point to wait message
      CALL   PSTR      ; Print it
      CALL   GCHRA     ; Get response
      CALL   PNEWL     ; Print new line
      CP     '.'       ; Is response a dot?
      JP     Z,QUES1   ; Yes then exit
      CP     SPAC      ; Is it a space?
      JR     NZ,READ   ; No then try again
      XOR    A         ; Clear A=Drive zero
      CALL   CASON     ; Switch on drive zero
      CALL   DELS      ; Short delay
      CALL   RDHDR     ; Read header from tape
      CALL   READC     ; Read first character
      LD     B,A       ; Put in B
      CALL   READC     ; Read second character
      LD     C,A       ; Place in C
      OR     B         ; BC now equals count
      JP     Z,NOSTR   ; Count zero, so exit
      LD     (COUNT),BC ; Set count = read count
      LD     HL,ARST   ; Point to start of store
ROWNR  PUSH   BC       ; Same count
      LD     E,Ø       ; E = Check sum for a row
      LD     B,6       ; B = Column Count
RDBYT  CALL   READC     ; Read a row element
      LD     (HL),A    ; Store it
      ADD   A,E        ; Add it to check sum
      LD     E,A       ; Store in check sum
      INC   HL         ; Inc memory pointer
      DJNZ  RDBYT     ; Do next element
      POP   BC         ; Restore row count
      CALL  READC     ; Read check digit
      CP     E         ; Same as calculated?
      JR     NZ,RDERR  ; No then error
      DEC   BC         ; Decrement row count
      LD     A,B       ; See if row count
      OR     C         ; is zero
      JR     NZ,ROWNR  ; No then read next row
      CALL  CASOF     ; Switch cassette off
      JP     TAPEF     ; exit
RDERR  LD     HL,RDMSG  ; Error message for tape
      CALL  PSTR      ; Print it
      JP     QUES1    ; Go to main loop
  
```



WRITE ROUTINE

; Writes a stored sequence to tape

WRITE	LD	BC, (COUNT)	; Get row count
	LD	A, B	;
	OR	C	;
BADWI	JP	Z, NOSTR	; If zero exit
	LD	HL, CASRD	; print message
	CALL	PSTR	;
	CALL	GCHRA	; Get answer
	CALL	PNEWL	; Print new line
	CP	'.'	; Is answer a dot
	JP	Z, QUES1	; Yes then exit
	CP	SPAC	; Is answer a space
	JR	NZ, BADWI	; No then try again
	XOR	A	; Clear drive number
	CALL	CASON	; Switch on drive zero
	CALL	DELT	; delay
	CALL	WRLDR	; Write Leader
	CALL	DELT	; delay
	LD	BC, (COUNT)	; Get count into BC
	LD	A, B	;
	CALL	WRBYA	; Write higher byte
	LD	A, C	; Get lower byte of count into A
	CALL	DELT	; delay
	CALL	WRBYA	; Write lower byte
ROWNW	LD	HL, ARST	; Point to start of sequence of store
	PUSH	BC	; Save row count
	LD	E, Ø	; Clear check sum
	LD	B, 6	; Six motor slots per row
WRBYT	LD	A, (HL)	; Get motor slot N
	CALL	DELS	; delay
	CALL	WRBYA	; Write it
	CALL	DELS	; delay
	ADD	A, E	; add to check sum
	LD	E, A	;
	INC	HL	; Inc memory pointer
	DJNZ	WRBYT	; Do for all six motors
	CALL	WRBYA	; Write check sum
	POP	BC	; Restore row count
	DEC	BC	; Decrement row count
	LD	A, B	;
	OR	C	; Test if zero
	JR	NZ, ROWNW	; No then try again
	CALL	CASOF	; Switch cassette off
	JP	QUES1	; Back to main loop

## CHECK ROUTINE

; Checks tape with sequence in store

CHECK	LD	BC, (COUNT)	; Get row count
	LD	A, B	;
	OR	C	;
	JP	Z, NOSTR	; If zero exit
BADCI	LD	HL, CASRD	; Print wait message
	CALL	PSTR	;
	CALL	GCHRA	; Get answer
	CALL	PNEWL	; Print new line
	CP	'.'	; Is response a '.'
	JP	Z, QUES1	; Yes then go to main loop
	CP	SPAC	; Is it a space
	JR	NZ, BADCI	; No then try again
	XOR	A	; Clear cassette number
	CALL	CASON	; Switch drive zero on
	CALL	RDHDR	; Read header from tape
	LD	BC, (COUNT)	; Get row count
	CALL	READC	; Read first section
	CP	B	; Same?
	JR	NZ, RDERR	; No then error
	CALL	READC	; Read lower byte of count
	CP	C	; Same?
	JR	NZ, RDERR	; No then error
	OR	B	; Zero count from tape
	JP	Z, NOSTR	; So exit
	LD	HL, ARST	; Point to start of memory
ROWNC	PUSH	BC	; Save count
	LD	E, 0	; Check sum is zero
	LD	B, 6	; Count is 6
CKBYT	CALL	READC	; Read a motor step element
	CP	(HL)	; Same as in store?
	JP	NZ, RDERR	; Not the same so error
	ADD	A, E	;
	LD	E, A	; Add to check sum
	INC	HL	; Advance memory pointer
	DJNZ	CKBYT	; Do next row element
	POP	BC	; Restore row count
	CALL	READC	; Read check sum
	CP	E	; Same as check sum calculated
	JP	NZ, RDERR	; No then error
	DEC	BC	; Decrement count
	LD	A, B	;
	OR	C	; Is count zero?
	JP	NZ, ROWNC	; No then do next row
	CALL	CASOF	; Switch cassette off
TAPEF	LD	HL, TAPOK	; Print tape off message
	CALL	PSTR	;
	JP	QUES1	; and back to main loop



BOOT AND FINISH COMMANDS

; This routine restarts the program

```

BOCT      LD      HL,BOOTS      ; Print "DO YOU REALLY
          CALL    PSTR          ; WANT TO RESTART?"
          CALL    GCHRA         ; Get answer
          CP      'Y'          ; User typed 'Y'?
          JP      Z,STARM       ; Yes then restart program
          CP      'N'          ; No 'N'?
          JR      NZ,BOCT       ; Then try again
          CALL    PNEWL         ; else print new line and
          JP      QUES1         ; back to main loop
    
```

; This is the exit from program Section to TRS80  
; system level

```

FINSH     LD      HL,RELYQ      ; Print "REALLY QUIT"
          CALL    PSTR          ;
          CALL    GCHRA         ; Get answer
          CP      'Y'          ; User typed a 'Y'
          JR      NZ,TRYNO      ; No then try 'N'
          LD      HL,SIGOF      ; Print ending message
          CALL    PSTR          ; and then
          JF      FINAD         ; return to TRS80 System
TRYNO     CP      'N'          ; User typed an 'N'
          JR      NZ,FINSH      ; No then try again
          CALL    PNEWL         ; Print a new line
          JP      QUES1         ; Back to main loop
    
```

#### OTHER SHORT COMMANDS

; SETAM: clears arm position array

```
SETAM    CALL    RESET    ; Clear Arm array (POSAR)
         JP      QUES1    ; Back to main loop
```

; TOSTM moves the arm back to its start position

```
TCSTM    CALL    MOVTO    ; Steps motors till POSAR elements
         JP      QUES1    ; are zero then back to main loop
```

; FREARM frees all motors for user to move arm  
; by hand

```
FREARM   CALL    CLRMT    ; Output all ones to motors
         JP      QUES1    ; and now to main loop
```

; MANU allows the user to move the arm using  
; the 1-6 keys and the 'Q' 'W' 'E' 'R' 'T' 'Y' keys  
; The movements made are not stored.

```
MANU     LD      A,1      ; Set in manual mode for the
         LD      (MAN),A  ; keyin routine
MANUA    CALL    KEYIN    ; Now get keys and move motors
         JP      NZ,MANUA; If non zero then move to be done
         XOR     A        ; Clear manual flag
         LD      (MAN),A  ;
         JP      QUES1    ; Back to main loop
```



## THE GO COMMAND

```

; This command causes the computer to step
; through a stored sequence and makes the arm
; follow the steps stored, if the sequence is to
; be done fcrever then the arm resets itself at
; the end of each cycle.

GO      CALL    PNEWL      ; Print a new line
        CALL    MOVTO     ; Move arm to start
        XOR     A         ; Clear
        LD     (FORFG),A  ; Forever Flag FCFPG
        LD     HL,AORNM   ; Print "DO ONCE OR FCREVER
        CALL    PSTR      ; Message
        CALL    GCHRA     ; Get answer and print it
        CALL    PNEWL     ; Print a new line
        CP     'O'        ; User typed an 'O'
        JR     Z,ONECY    ; Do sequence till end
        CP     'F'        ; User typed an 'F'
        JF     NZ,GO      ; No then re-try
        LD     A,1        ; Set fcrever flag
        LD     (FORFG),A  ; to 1
ONECY   LD     A, '.'     ; Print a '.'
        CALL    PUTCHR    ; Using PUTCHR
        CALL    DCALL     ; Execute the sequence
        LD     A,(FORFG)  ; Test FORFG, if zero
        OR     A          ; then we do not want
        JF     Z,NCRET    ; to carry on so exit
        CALL    DELT      ; delay
        CALL    MOVTO     ; Move arm to start
        CALL    DELLN     ; Delay approx 1 second
        JR     ONECY      ; Do next sequence
NCRET  LD     HL,DONMS    ; Print sequence done
        CALL    PSTR      ;
        JP     QUES1      ; and go to main loop

```

## THE DISPLAY COMMAND

```
; This command allows the user to display
; the motor sequence so that he can then
; alter the contents of a sequence by using
; the edit command
```

```
DISP      LD      HL,DISPS      ; Point to header string
          CALL    PSTR          ; and display it
          CALL    POSDS        ; Print out the relative position
          LD      HL,ARST      ; Point to sequence start
          LD      BC,(COUNT)  ; BC = how many rows to print
          LD      A,B          ;
          OR      C            ; Test if count is zero
          JP      NZ,SETBC     ; No then jump to rest of
NOSTR     LD      HL,NODIS     ; display else print message
          CALL    PSTR          ; telling user no display and
          JP      QUES1        ; return to the main loop
SETBC     LD      EC,0000      ; Clear BC for row count
DORCW    PUSH    EC            ; Save it
          PUSH    HL            ; Save memory position
          LD      H,B          ;
          LD      L,C          ; HL = row count
          INC     HL            ; Now row count =N+1
          LC      LX,NUMAR     ; LX points to buffer for ASCII String
          CALL    CBTAS        ; Convert HL to ASCII
          LC      HL,NUMAR     ; Point to ASCII string
          CALL    PSTR          ; now print it
          LD      A,'.'        ;
          CALL    PUTCHR       ; Print a '.'
          POP     HL            ; Restore memory pointer
          LD      B,6           ; Motor count to B (6 motors)
NEXTE    LD      A,(HL)        ; Get step value
          PUSH    HL            ; Save memory pointer
          PUSH    BC            ; Save motor count
          EJT     7,A          ; Test bit 7 of A for sign
          JR      Z,NUMPO      ; If bit = 0 then positive step
          LD      H,0FFH       ; Make H = negative number
          JR      EVAL         ; Do rest
NUMPO    LD      H,0           ; Clear H for positive number
EVAL     LD      L,A           ; Get low order byte into L
          LD      LX,NUMAR     ; Point to result string
          CALL    CBTAS        ; Call conversion routine
          LD      HL,NUMAR     ; HL points to result
          CALL    PSTR          ; Print resulting conversion
          LD      A,(3810H)    ; Get keyboard memory location
          BIT     0,A          ; Test for zero key pressed
          JR      Z,NOSTP      ; Not pressed, then skip
DOSTF    CALL    GCHR          ; Wait till next character entered
          CP      '.'          ; Is it a dot?
          JR      NZ,NOSTP     ; No then carry on
          CALL    PNEWL        ; else print a new line
          POP     BC            ; and restore all the registers
          POP     HL            ; and the stack level
```



NOSTP

```
POP      BC      ;
JP       QUES1   ; Jump back to main loop
POP      BC      ; Restore column count
POP      HL      ; Restore memory pointer
INC      HL      ; Increment memory pointer
CALL     PSPAC   ; Print a space between
           ; numbers
DJNZ     NEXTE   ; Do for six motors
CALL     PNEWL   ; Print a new line
POP      BC      ; Restore row count
INC      BC      ; Increment row count
LD       A,(COUNT) ; Get lower count byte
CP       C       ; Is it the same
JR       NZ,DOROW ; No then do next row
LD       A,(COUNT+1) ; Get higher order count byte
CP       B       ; Same?
JR       NZ,DOROW ; No then do next row else
CALL     PNEWL   ; print a new line and then
JP       QUES1   ; back to main loop
```

## SUBROUTINES INDEX

DOALL.....Execute a stored sequence once  
DRIVL.....Drives all motors directed by TBUF  
INIT.....Set up system  
MOVTO.....Use PCSAR to rest system arm  
TORQUE.....Turn on off motors  
CLRMT.....Turn off all motors  
SETCT.....Reset CTPOS elements to one  
DRAMT.....Drive directed motors  
STEPM.....Step motors via DRAMT  
DNEWB.....Delay on direction change  
SPAMT.....Update TBUF array during learn  
KEYIN.....Scan keyboard and build up motors to move  
CBTAS.....Convert 16 bit 2's complement number to ASCII  
CLRMP.....Clear MOTBF array  
CTBUF.....Clear TBUF, DRBUF & MOTBF arrays  
GINI.....Get 16 bit signed value from keyboard  
POSDS.....Display relative position array elements  
POSJC.....Increment relative position array elements  
STORE.....Copy TBUF to current ARST slice  
RESET.....Clear POSAR array  
PUTCHR.....Print a character  
PSTR.....Print a string  
PSPAC.....Print a space  
PNEWL.....Print a carriage return



S E C T I O N 3

S  
U  
B  
R  
O  
U  
T  
I  
N  
E  
S.

SUBROUTINES INDEX (continued)

SCKBE.....Scan the keyboard  
GCHPA.....Get a character and print it  
CLRSC.....Clear the Screen  
DELSW.....Delay on value in B  
DELS.....Delay approx 0.001 sec  
DELT.....Delay approx 0. 01 sec  
DELLN.....Dealy approx 1. 0 sec



SUBROUTINE DOALL

; This subroutine executes a sequence in store cnce.  
 ; Forever flag FORFG is cleared if user types a '.'

DOALL	LD	BC,(COUNT)	; Get sequence row count.
	LD	A,B	;
	OR	C	; If count zero then
	JR	Z,RET2	; exit
	LD	HL,ARST	; HL points to memory start
NMOTS	LD	DE,TBUF	; DE points to temporary buffer
	PUSH	BC	; Save count
	LD	EC,0006	; Motor count of six
	LFIR		; Copy memory slice into TBUF
	PUSH	HL	; Save new memory pointer
	CALL	DRIVL	; Drive all motors for this slice
	CALL	SCKBD	; See if keyboard input
	POP	HL	; Restore memory pointer
	POP	BC	; Restore row count
	CALL	DNEWB	;
	CP	'.'	; User typed a '.'
	JR	NZ,CARON	; No then continue
RET2	XOR	A	; Clear A
	LD	(FORFG),A	; Clear flag to halt routine above
	RET		; exit
CARON	DEC	BC	; Decrement count
	LD	A,B	;
	OR	C	; Test for zero
	JR	NZ,NMOTS	; No then carry on else
	RET		; return

SUPERROUTINE DRIVL

; This routine is given TBUF, it then drives all  
 ; the motors that need to be driven, till TBUF = 0

```

DRIVL      LD      C,0      ;
SCANW     LD      E,6      ; Set BC = motor count
          LD      HL,TBUF   ; Point to TBUF
TBZER     LD      A,(HL)    ; Get step value from TBUF
          OR      A         ; Is it zero?
          JR      NZ,TBNZR  ; No then continue
          INC     HL        ; Point to next TBUF location
          DJNZ   TBZER     ; Do next motor check
          RET      ; If no motor to step, then return
TBNZR     LD      DE,MOTBF + 5 ; DE points to last direction array
          LD      HL,TBUF + 5 ; HL points to TBUF
          LD      B,6      ; B = motor count
DOAGN     LD      A,(HL)    ; Get motor step value
          CP      0        ; Is it zero?
          JR      Z,NOEL   ; Yes then skip
          JP      M,SNeg   ; Is it negative ie, reverse
SPOS      LD      A,3      ; No positive, so load MOTBF (N)
          LD      (DE),A    ; With 3
          DEC     (HL)     ; Decrement motor count in TBUF
          JR      NOFIL    ; Complete the MOTBF array
SNeg      LD      A,1      ; Set MOTBF = 1 for
          LD      (DE),A    ; a positive drive
          INC     (HL)     ; Decrement negative count
          JR      NOFIL    ; Do rest of MOTBF
NOEL      XOR     A         ; Clear MOTBF (N)
          LD      (DE),A    ;
NOFIL     DEC     DE       ; Move to next MOTBF element
          DEC     HL        ; Move to next TBUF element
          DJNZ   DOAGN     ; Do for all six motors
          LD      A,1      ;
          LD      (KEYP),A  ; Set key pressed flag
          CALL   STEPM     ; Step all motors once if
          DEC     C         ; any to step
          JF     NZ,SCANW  ; Do for maximum of 128 cycles
          RET      ; then return
  
```

SUBROUTINE INIT

; INIT clears the row count (COUNT), resets the  
; MAN flag, clears the TBUF, DRBUF, & MOTBF arrays  
; The CUROW pointer is reset to the start of the ARST,  
; position array is cleared.

```
INIT      LD      HL,Ø      ; Set HL = Ø
          LD      (COUNT),HL ; and clear the row count
          XOR     A          ; Clear A
          LD      (MAN),A    ; Now clear MAN
          LD      HL,ARST    ; HL = start of arm store
          LD      (CURCW),HL ; CUROW = start of arm store
          CALL    CTBUF      ; Clear TBUF, DRBUF & MOTBF
          CALL    RESET     ; Clear the POSAR array
          CALL    CLFMT     ; Free all motors
          RET              ; EXIT
```



SUBROUTINE MOVIC

; This routine takes the POSAR array and uses it to drive  
 ; all the motors until the ARM is in its defined start position

```

MOVTO    PUSH    AF          ; *
         PUSH    BC          ; *
         PUSH    LE          ; *   Save registers
         PUSH    HL          ; *
RES1     LD     HL,POSAR     ; HL points to POSAR
         LD     B,12        ; B = count of 12
NRES1    LD     A,(HL)       ; Get FCSAR element
         OR     A           ; Is it zero?
         JR     NZ,MTSA     ; No then continue
         INC    HL          ; Point to next POSAR element
         DJNZ  NRES1       ; See if all zero
         JR     ENDS        ; All zero so end!
MTSA     LD     HL,FCSAR+10  ; HL points to POSAR
         LE    DE,MOTBF+ 5  ; DE points to MOTBF
         LE    B,6          ; B = count
RSCAN    PUSH    BC          ; Save count
         LD     C,(HL)      ; Get lower byte
         INC    HL          ; Advance HL pointer
         LD     B,(HL)      ; Get high byte of POSAR element
         LD     A,C         ; Get low byte into A
         OR     B           ; See if POSAR(N) is zero
         JP     NZ,DOMPL    ; no skip
         LD     (DE),A      ; Zero MOTBF (N)
         DEC    HL          ; advance POSAR pointer
         JR     NMDR        ; Do next motor
DOMFL    LD     A,B         ; See direction to move in
         BIT    7,A         ;
         JR     Z,RMOT1    ; Go in reverse
         INC    BC          ; Go forward
         LD     A,1         ; A = forward
         JR     DOIT1      ; Do rest
RMOT1    DEC    EC         ; Dec count for reverse
         LD     A,3         ; Set reverse in A
DOIT1    LD     (DE),A      ; Store reverse in MOTBF (N)
         LD     (HL),B      ; Store updated POSAR count
         DEC    HL          ; in POSAR (N)
         LD     (HL),C      ; Store lower byte
NMDR     DEC    HL          ;
         DEC    HL          ; point to next POSAR element
         DEC    DE          ; Move to next MOTBF element
         POP    BC          ; Restore motor count
         DJNZ  RSCAN       ; Do for next motor
         CALL  DRAMT       ; Drive all motors to be driven
         JR     RES1       ; Do till all POSAR slots zero
ENDSC    POP    HL          ; *
         POP    DE          ; *
         POP    BC          ; *   Restore all registers
         POP    AF          ; *
         RET                ; Return
  
```

SUBROUTINES TORQUE, CLRMT AND SETDT

; TORQUE switches of motors on and sets CTPOS(N)'s  
 ; CLRMT turns all motors off and sets CTPCS(1-6)  
 ; SETDT sets all CTPOS elements to start offset  
 ; position which equals 1.

```

TORQUE    PUSH    AF      ; * Set clear motor-
          PUSH    BC      ; *
          PUSH    DE      ; * Save Registers
          PUSH    HL      ; *
          LD     HL,TORMS ; Print TORQUE ON message
          CALL   PSTR     ;
          LD     DE,CTPOS ; Point to FTABL offset array
          LD     HL,MOTBF ; Point to last drive table
          LD     B,6      ; B = motor count
TORQ1     LD     A,(HL)   ; Get motor value
          OR     A        ; Is it zero?
          JR     NZ,TORQ2 ; No then skip
          LD     A,1      ; Reset CTPOS(N) to position 1
          LD     (DE),A   ; in FTABL
          LD     A,B      ; Get motor address in A
          SLA   A        ; Shift it left for interface defn
          OR     192     ; or in FTABL pulse
          OUT   (PORT),A ; Output it to selected motor
TORQ2     INC    DE      ; Advance points to next
          INC    HL      ; motors
          DJNZ  TORQ1    ; Do next motor
          JR     TOQCL   ; Exit with register restoration
CLRMT     PUSH    AF      ; * clear all motors torque
          PUSH    BC      ; *
          PUSH    DE      ; * Save Registers
          PUSH    HL      ; *
          LD     HL,NOTOR ; Print "NO TORQUE" message
          CALL   PSTR     ;
          LD     D,ØFØH   ; Pattern for motors off
OTMT      LD     B,6      ; B = Motor count
CLNT      LD     A,B      ; Get motor address in A
          SLA   A        ; Shift into correct bit position
          OR     D        ; Combine with coils off pattern
          OUT   (FORT),A ; Output to selected motor
          DJNZ  CLNT     ; Do next motor
          CALL  SETDT    ; Clear CTPOS array to value of 1
TOQCL     POP    HL      ; *
          POP    DE      ; *
          POP    BC      ; * Restore Registers
          POP    AF      ; *
          RET           ; Done, exit
  
```

```

SETDT    PUSH    BC      ; * Set CTPOS elements to start
          PUSH    DE      ; * Save used registers
          PUSH    HL      ; *
          LD      B,6      ; Motor count to B
          LD      HL,CTPOS ; HL points to CTPOS array
NSET1    LE      (HL),1    ; Set CTPOS(N) to start position = 1
          INC     HL      ; Increment HL
          DJNZ   NSET1    ; Do set up next CTPOS element
          POP     HL      ; *
          POP     DE      ; * Restore used registers
          POP     BC      ; *
          RET            ;

```



SUBROUTINE DRAMT

; DRAMT drives all six motors directly and uses  
 ; FTABL to output the correct pulse patterns.  
 ; For half stepping the pattern must be changed in FTABL  
 ; and the bounds in DRAMT

```

DRAMT      PUSH  AF          ; *
           PUSH  BC          ; *
           FUSH  DE          ; * Save Registers
           PUSH  HL          ; *
           LD    B,6         ; B = motor count
           LD    DE,MOTBF +5 ; Point to MOTBF array
           LD    HL,CTPOS    ; HL points to FTABL offset array
NMTDT      LD    A,(DE)      ; Get MOTEF(N)
           OR    A           ; Is it zero?
           JR    Z,IGMTN    ; If zero, then skip
           BIT   1,A         ; Test direction
           CALL  OUTAM      ; Step motor
           JR    Z,REVMT    ; If direction negative then jump
           INC  A           ; Increment table counter
           CP   5           ; Upper bound?
           JR   C,NORST    ; No then continue
           LD   A,1        ; Reset table offset
NORST      LD   (HL),A      ; Store in CTPOS (N)
IGMTN      INC  HL          ; Increment CTPOS pointer
           DEC  DE          ; Decrement MOTBF pointer
           DJNZ NMTDT      ; Do for next motor
           CALL DELT        ; Delay after all pulses out
           CALL DELS        ; *
           POP  HL          ; *
           POP  DE          ; *
           POP  BC          ; * Restore Registers
           POP  AF          ; *
           RET              ; Exit
REVMT      DEC  A           ; Move table pointer on
           CP   1           ; Compare with lower bound
           JR   NC,NORST   ; If no overflow then continue
           LD   A,4        ; Reset table offset
           JR   NORST      ; Do next motor
OUTAM      LD   A,(HL)     ; Get table offset 1-4
           PUSH AF          ; *
           PUSH DE          ; * Save Registers
           PUSH HL          ; *
           LD   HL,FTABL-1 ; Get table start
           LD   D,0         ;
           LD   E,A         ; DE now equals 1-4
           ADD  HL,DE       ; Add to FTABL -1 to get address
           LD   A,(HL)     ; Get motor pulse pattern
           LD   C,B         ; Get address field in C and
           SLA  C           ; shift it one to the left
           OR   C           ; or in the pulse pattern
           CUT  (PCRT),A    ; Output to interface circuitry
           POP  HL          ; *
           POP  DE          ; * Restore Registers
           POP  AF          ; *
           RET              ; Return
  
```

SUBROUTINE STEPM

; This routine causes all motors that should be  
 ; stepped to be so, and updates the motors relative  
 ; positions from their start positions.

```

STEPM      PUSH  AF          ; *
           PUSH  HL          ; * Save Register
           PUSH  BC          ; *
           LD    HL,MOTBF    ; HL points to motor buffer
           LD    B,6         ; B = Ccount
TRYØ       LD    A,(HL)      ; Get motor value 3 or 1
           OR    A           ; Zero?
           JR    NZ,CONTA    ; No then continue
CCNT       INC    HL         ; Point to next motor
           DJNZ  TRYØ        ; Do next motor
           POP   BC          ; *
           POP   HL          ; * Restore Registers
           POP   AF          ; *
           RET              ; Exit
CONTA     PGP   BC          ; *
           POP   HL          ; * Restore registers
           CALL  DRAMT       ; Drive motors
           CALL  POSIC       ; Increment relative position
           PCF   AF          ; * Restore AF
           RET              ; Exit
  
```

SUBROUTINE DNEWD

; This subroutine checks to see if any motors are  
 ; changing direction , if so a delay is inserted  
 ; into the sequence.

```

DNEWD  PUSH  AF          ; *
        PUSH  BC          ; *
        PUSH  DE          ; * save used registers
        PUSH  HL          ; *
        LD   BC,6         ; Load BC with count
        OR   A            ; Clear carry
        SBC  HL,BC        ; HC points to previous motor slice
        LD   D,H          ;
        LD   E,L          ; Move HL to DE
        POP  HL           ; Restore current row pointer
        PUSH HL           ; Save again
        LD   B,C          ;
NCOMP  LD   A,(HL)        ; Get contents of this row
        CP   Ø            ; See if positive or negative
        LD   A,(DE)       ; Get identical previous motor slot
        JP   P,PDIR       ; if positive do for positive motor
NDIR   CP   Ø            ; Compare if both in same
        JP   M,NXTCK      ; direction then skip else
CDDEL  CALL  DELLN        ; delay and
NCDSG  POP  HL           ; *
        POP  DE           ; *
        POP  BC           ; * Restore registers
        POP  AF           ; *
        RET              ; Now return
PDIR   CP   Ø            ; If previous motor is negative
        JP   P,NXTCK      ; then delay, else do for next
        JR   CDDEL        ; motor slot
NXTCK  INC  HL           ; increment current row pointer
        INC  DE           ; increment lost row pointer
        DJNZ NCMP         ; do for next motor
        JR   NCDSG        ; Return with no large (1 sec) delay
  
```



SUBROUTINE SRAMT

; SRAMT is responsible for updating the TBUF  
 ; elements and for setting the STRFG if a situation  
 ; exists where the TBUF array should be stored in the  
 ; current ARST slot. This will occur if any motor changes  
 ; direction or a motor exceeds the allowed slct  
 ; boundary of -128 to 127.

```

SRAMT      LD      A,(MAN)      ; Get manual flag
           OR      A           ; Is it zero?
           JP      NZ,STEPM    ; Yes then just step motors
           LD      (STRFG),A   ; Clear the store flag
           LD      B,6         ; B = motor count
           LD      LX,DRBUF+6  ; LX = previous direction buffer
           LD      LY,MOTBF+6  ; LY = current buffer
           LD      HL,TBUF +6  ; HL = step buffer
NTMOT      DEC     LY          ;
           DEC     LX          ;
           DEC     HL          ; move pointers
           LD      A,(LY +0)   ; Get current motor direction
           OR      A           ; No work to do
           JR      Z,NODRV     ; skip, if so
           CP      1          ; Reverse
           JR      Z,REVDR     ; Yes then skip
FORDR      LD      A,(LX+0)    ; Get previous direction
           CP      1          ; Direction change?
           JR      NZ,CFORD    ; No then advance TBUF(N) step
           CALL   SETST       ; Set the store flag
           LD      (LY+0),0    ; Clear MCTEF element.
           JR      NODRV      ; Do next motor
CFORD      INC     (HL)       ; Increment rotor step in TBUF
           LD      A,(HL)     ; Get new value
           CP      127        ; Check against upper board
           CALL   SETST       ; Limit reached then store flag
           LD      (LX+0),3    ; Set previous direction
NODRV      DJNZ   NTMOT       ; Do next motor
           CALL   STEPM       ; Step motors to be driven
           LD      A,(STRFG)  ; Examine store flag
           OR      A           ; Zero?
           JP      NZ,STORE   ; No then do store operation
           RET                ; Exit
REVDR     LD      A,(LX+0)    ; Get previous direction
           CP      3          ; Direction reversed?
           JR      NZ,CREV1   ; No then continue
           CALL   SETST       ; Else set store TBUF in ARST flag
           LD      (LY+0),0    ; clear MCTEF element
           JR      NODRV      ; Do next motor
CREV1     DEC     (HL)       ; Advance step count in TBUF (N)
           LD      A,(HL)     ; Get element
           CP      -128       ; Compare with upper negative bound
           CALL   Z,SETST     ; Limit reached so set store flag
CREVD     LD      (LX+0),1    ; Set Direction
           JR      NODRV      ; Do next motor
SETST     PUSH   AF          ; Save AF
           LD      A,1        ; Set store flag STRFG
SETSC     LD      (STRFG),A   ; to one
           POP    AF          ; Restore AF
           RET                ; Continue
  
```

SUBROUTINE KEYIN

; This routine scans the keyboard checking for  
 ; the keys '1-6' and 'Q' 'W' 'E' 'R' 'T' 'Y' and 'S'  
 ; and Ø. It then drives the motors corresponding  
 ; to the keys pressed. If in learn mode the  
 ; sequence is stored.

```

KEYIN      CALL      CLRMF      ; Clear MOTBF array
           LD        A,(384ØH) ; Get TRS8Ø keyboard byte
           BIT       7,A        ; See if
           JR        Z,IGDEL    ; No space key so skip
           CALL      DELT       ; *
           CALL      DELT       ; * Slow motor driving
IGDEL      XOR       A          ; Clear KEY PRESSED flag
           LD        (KEYP),A   ;
           LD        A,(381ØH) ;
           BIT       Ø,A        ; Is the zero key pressed?
           JR        Z,TRYS     ; No then skip
           JP        NOTNG      ; Go to do nothing
TRYS       LD        A,(38Ø4H) ; See if
           BIT       3,A        ; 'S' key pressed
           LD        A,(381ØH) ; Restore memory value
           JR        Z,TRYN1    ; No then skip
           LD        A,(MAN)    ; See if in manual mode
           CR        A          ;
           CALL      Z,STORE    ; No then store TBUF
           OR        1         ; Set not finished flag
           RET        ; and exit to caller
TRYN1      LD        BC,Ø       ; Clear MOTBF offset in BC
           BIT       1,A        ; See if '1' key is pressed
           JP        Z,TRYN2    ; No then skip else
           CALL      FORMT      ; Set up motor 1 position in MOTBF
TRYN2      INC       BC         ; Increment MOTBF offset
           BIT       2,A        ; See if '2' key pressed
           JP        Z,TRYN3    ; No skip
           CALL      FORMT      ; Set second motor forward
TRYN3      INC       BC         ; Advance offset
           BIT       3,A        ;
           JP        Z,TRYN4    ; See if '3' key pressed, No skip
           CALL      FORMT      ; Set forward direction on Motor 3
TRYN4      INC       BC         ; Increment offset in BC
           BIT       4,A        ; See if key '4' is pressed
           JP        Z,TRYN5    ; No then test key '5'
           CALL      FORMT      ; Do forward direction for Motor 4
TRYN5      INC       BC         ; Advance offset
           BIT       5,A        ; Key '5' pressed
           JP        Z,TRYN6    ; No skip
           CALL      FORMT      ; Do set up for motor 5
TRYN6      INC       BC         ; Advance offset
           BIT       6,A        ; Key '6' pressed
           JP        Z,TRYQT    ; No then try 'Q'
           CALL      FORMT      ; Do for motor 6
  
```



```

TRYQT      LD      BC,0           ; Clear BC offset for motor 1
           LD      A,(3804H)      ; See if 'Q' key pressed
TRYQ       EIT     1,A           ;
           JP      Z,TRYW        ; No then skip
           CALL   BACMT         ; Set motor 1 for backward
TRYW       INC     BC           ; Advance pointer
           BIT    7,A           ; See if 'W' key pressed
           JP      Z,TYRE       ; No skip
           CALL   BACMT         ; Do backward for motor 2
TRYE       INC     BC           ; Advance pointer offset
           LD      A,(3801H)      ; See if
           BIT    5,A           ; 'E' key pressed
           JR      Z,TRYR       ; No skip
           CALL   BACMT         ; Set motor 3 for backward
TRYR       INC     BC           ; Advance pointer offset
           LD      A,(3804H)      ; See if
           BIT    2,A           ; Key 'R' is pressed
           JP      TRYT        ; No skip
           CALL   BACMT         ; Set motor 4 backward
TRYT       INC     BC           ; Advance offset
           BIT    4,A           ; Is key 'T' pressed?
           JP      Z,TRYR       ; No skip
           CALL   BACMT         ; Set motor 5 backward
TRYR       LD      A,(3808H)      ; Is the 'Y' key pressed?
           INC     BC           ; Advance offset
           BIT    1,A           ; No key
           JP      Z,SOMEN      ; 'Y' then skip
           CALL   BACMT         ; Set motor 6 for backward
SOMEN     CALL   SRAMT         ; Step motors, maybe store.
           OR     1             ; Set zero key not pressed flag
           RET     ; Return to caller
NOTNG     LD      A,(MAN)        ; Zero was pressed so see
           OR     A             ; if in learn mode
           CALL   Z,STORE       ; Yes then store
           XOR    A             ; Set zero flag and
           RET     ; Return to caller
FORMT     LD      E,3           ; Set for forward direction
           JR      SETMT        ; Do set motor slot in MOTBF
BACMT     LD      E,1           ; Set for reverse direction
SETMT     LD      HL,MOTBF      ; Point to MOTBF
           ADD    HL,BC         ; Add in motor offset
           PUSH   AF           ; Save AF
           LD      A,(HL)       ; Get byte
           OR     A             ; See if zero
           JR      Z,DOMOT      ; Yes then set byte
           XOR    A             ; Clear
           LD     (HL),A        ; byte in MOTBF user wants both
           POP    AF           ; directions clear byte
           RET     ; Restore AF and return
DOMOT     LD      (HL),E        ; Set byte in MOTBF
           LD     A,1           ; and set
           LD     (KEYP),A      ; key pressed flag
           POP    AF           ; Restore AF
           RET     ; exit from routine

```



SUBROUTINE CBTAS

; This subroutine makes a signed binary value in  
 ; HL into arm ASCII String and stores the string  
 ; in the locations pointed to by IX

```

CBTAS    PUSH    AF          ; *
         PUSH    HL          ; *
         PUSH    DE          ; *   Save Registers
         PUSH    IX         ; *
         BIT     7,H         ; Test sign of number
         JR     Z,POSNO     ; If zero then positive number
         LD     A,H         ;
         CPL          ; Complement number if negative
         LD     H,A         ;
         LD     A,L         ;
         CPL          ;
         LD     L,A         ;
         INC    HL          ; Now 2's complement negative
         LD     A,MINUS     ; Place minus sign in string
PUTSN    LD     (IX+0),A    ; Pointed to by IX
         INC    IX         ; Advance IX pointer
         JR     CONUM       ; Do rest of conversion
POSNO    LD     A,SPAC     ; Place a space if number positive
         JR     PUTSN      ; Jump to copy space to memory
CONUM    PUSH    LY         ; Save LY register
         LD     LY,BTOAT   ; Point to subtraction table
NUMLP    LD     A,NUMBA     ; Get ASCII 0 in A
         LD     E,(LY+0)   ;
         LD     D,(LY+1)   ; Get table value
SUBBA    OR     A           ; Clear carry bit
         SBC    HL,DE      ; Subtract table value from value
         ; input
         JP     C,GONEN    ; If carry then do for next digit
         INC    A           ; Inc count (ASCII in A)
         JR     SUBBA      ; Do next subtraction
GONEN    ADD    HL,DE       ; Restore value before last
         ; subtraction
         LD     (IX+0),A    ; Store ASCII Number in memory
         INC    IX         ; Inc memory pointer
         INC    LY         ; Point to next table value
         INC    LY         ;
         DEC    E           ; Test if E = 0
         JR     NZ,NUMLP   ; No then try for next digit
         XOR    A           ; Clear A and place in store
         LD     (IX+0),A    ; as EOS = End of string
         POP    LY         ; *
         POP    IX         ; *
         POP    DE         ; *   Restore all saved registers
         POP    HL         ; * and
         POP    AF         ; *
         RET          ; Exit
  
```



## CLEARING AND RESETTING ROUTINES

; CLRMF clears the MOTBF array

```

CLRMF    PUSH    BC           ; *
         PUSH    DE           ; * Save Registers used
         POP     HL           ; *
         LD     HL,MOTBF      ; Point to MOTBF(0)
         LD     DE,MOTBF +1   ; Point to MOTBF(1)
         LD     BC,5         ; BC = Count
         LD     (HL),0        ; MOTBF (0) = 0
         LDIR                    ; Copy through complete array
         POP     HL           ; *
         POP     DE           ; * Restore Registers used
         POP     BC           ; *
         RET                    ; Exit

```

; CTBUF clears TBUF, DRBUF and MOTBF  
; Note all must be in order

```

CTBUF    PUSH    BC           ; *
         PUSH    DE           ; * Save Registers
         PUSH    HL           ; *
         LD     HL,TBUF       ; HL points to TBUF(0)
         LD     DE,TBUF + 1   ; DE points to TBUF(1)
         LD     BC,17        ; BC = Count of 17
         LD     (HL),0        ; Clear first element
         LDIR                    ; Now clear next 17 elements
         POP     HL           ; *
         POP     DE           ; * Restore Registers
         POP     BC           ; *
         RET                    ; Exit

```



SUBROUTINE GINT

; This subroutine gets a signed 16 bit integer  
 ; from the TRS80 Keyboard.  
 ; If a bad number is typed it returns with the  
 ; Status flag - non zero.  
 ; The 2's complement number is returned in HL

```

GINT      PUSH    BC      ; *
          PUSH    DE      ; * Save Registers
          XOR     A        ; Clear A and carry
          SBC    HL,HL     ; Zero HL
          LD     B,5      ; Maximum of 5 characters
          LD     (MIN),A   ; Clear MIN=Minus Flag
GINT1     CALL   GCHRA    ; Get a character and display it
          CP     SPAC     ; Is it a space?
          JR     Z,GINT1   ; Yes then skip
          CP     NL       ; Is it a newline?
          JP     Z,PRET1   ; Done if new line, return zero
          CP     MINUS    ; A minus number?
          JF     NZ,POSON  ; No then see if positive
          LD     A,1      ; Set minus flag
          LD     (MIN),A   ;
          JR     GINT2     ; Get rest of number
PCSON     CP     '+'      ; Is number a positive number
          JR     NZ,NUM1   ; See if numeric
GINT2     CALL   GCHRA    ; Get next character
NUM1      CP     NL       ; Newline?
          JR     Z,NUMET   ; Yes then exit
          ADD    HL,HL     ; Double number
          PUSH   HL       ; Save X 2
          ADD    PL,HL     ; X 4
          ADD    HL,HL     ; X 8
          POP    DE       ; Restore X 2
          ADD    HL,DE     ; Now add to get X 10
          CP     0        ;
          JR     C,EFRN2   ; If number less than ASCII 0 ERR
          CP     '9' + 1  ; If number greater than ASCII
          JR     NC,EFRN2  ; 9 then error
          SUB    NUMBA    ; Number input OK, so make into
          LD     E,A      ; Binary and
          LD     D,0      ; load into DE
          ADD    HL,DE     ; Now add to total
          DJNZ  GINT2     ; Do for next digit
          CALL   PNEWL    ; Print a new line
NUMET     LD     A,(MIN)  ; Is number negative?
          OR     A        ;
          JR     Z,PRET1   ; No then finish off
          LD     A,L      ; else complement
          CPL     ; The value in HL
          LD     L,A      ;
          LD     A,H      ; (2's Complement)
  
```

```

CPL                ;
LD      H,A        ;
INC     HL         ;
PRET1   XOR     A   ; Clear A and flags
        PCP     DE ; * Restore Registers
        POP     BC ; *
        RET                    ; and return
ERRN2   CALL    PNEWL ; Print a newline
        LD     A,1 ; Set A to 1
        OR     A   ; Clear carry flag
        SBC   HL,HL ; Clear HL
        OR     A   ; Clear carry flag
        JR    PRET2 ; Return with ERROR CODE

```

SUBFOUNTINE POSDS

; This routine displays the POSAR array for the  
 ; user to see how far the arm is from its  
 ; "Home position"

```

POSDS      PUSH      AF          ; *
           PUSH      BC          ; *
           PUSH      DE          ; *   Save all registers
           PUSH      HL          ; *
           LD        HL,POSST    ; Print "RELPCS="
           CALL     PSTR         ; String
           LD        B,6         ; Motor count into B
NPCSA      LD        DE,POSAR    ; Point to array containing offsets
           LD        A,(DE)      ; Get lower order byte into
           LD        L,A         ; L
           INC       DE          ; Increment memory pointer
           LD        A,(DE)      ; Get higher order byte into
           LD        H,A         ; H
           INC       DE          ; Increment to next number
           LD        IX,NUMAR    ; IX points to result string
           CALL     CBTAS        ; Convert HL and leave in (IX)
           LD        HL,NUMAR    ; Point to result string
           CALL     PSTR         ; Print it
           CALL     PSPAC        ; Print a space
           DJNZ     NPCSA        ; Do for next motor
           CALL     PNEWL        ; Print a new line, all done
           POP       HL          ; *
           POP       DE          ; *
           POP       BC          ; *   Restore all Registers
           POP       AF          ; *
           RET                ; Now return
  
```



SUBROUTINE PCSIC

; PCSIC increments the signed 2's complement 16 bit  
 ; motor step offset counts. It does not check for overflow,  
 ; but this is very unlikely. The base would need to  
 ; be rotated about 2<sup>0</sup> times to cause such an event.

```

PCSIC      PUSH    AF          ; *
           PUSH    BC          ; *
           PUSH    DE          ; *   Save registers
           PUSH    HL          ; *
           LD      B,6         ; B = motor count
           LD      DE,MOTBF+5 ; Point to MOTBF
           LD      HL,POSAR+10; Point to POSAR (relative position)
NPOS1     FUSH    BC          ; Save motor count
           LD      C,(HL)      ; Get lower PCSAE byte in C
           INC     HL          ; Point to Higher byte
           LD      B,(HL)      ; Get higher byte in B
           LD      A,(DE)      ; Get direction byte from MOTBF
           AND     3           ; Clear all higher bits from D7-D3
           OR      A           ; Is it zero?
           JR      NZ,NONZM    ; No skip
           DEC     HL          ; Yes then move POSAR pointer back
           JR      NPOS2      ; and continue with next motor
NCNZM     BIT     1,A         ; Test direction bit
           JR      NZ,RDPOS    ; Do for reverse direction
           INC     BC          ; Advance element
           JR      STPCS      ; Restore 16 bit POSAR element
RDPOS     DEC     BC          ; Advance negative POSAR element
STPOS     LD      (HL),B      ; Store higher byte
           DEC     HL          ; Move pointer to lower byte
           LD      (HL),C      ; Store lower byte
NPOS2     DEC     HL          ; Back up PCSAR pointer to
           DEC     HL          ; next motor position slot
           DEC     DE          ; Backup MOTBF pointer to next slot
           POP     BC          ; Restore Motor count
           DJNZ   NPOS1      ; Do next motor
           POP     HL          ; *
           POP     DE          ; *   Restore used Registers
           POP     BC          ; *
           POP     AF          ; *
           RET                    ; Done, Exit
  
```

SUBROUTINE STORE

; STORE copies the TBUF array into the locations pointed to  
 ; by CURCW. If the TBUF array is completely empty then the  
 ; copy is not done. The COUNT and the CUROW variables  
 ; are both updated, and a check is made to ensure that  
 ; a store overflow is caught and the user told.

```

STORE    PUSH    BC      ; *
         PUSH    HL      ; * Save registers
         LD     HL,TBUF  ; Point to TBUF
         LD     B,6     ; B = motor count
STEST    LD     A,(HL)   ; Get TBUF (N)
         OR     A       ; Is TBUF element zero
         JR     NZ,STOR1 ; No then do store
         INC    HL      ; Point to next element
         DJNZ  STEST    ; Go do next element check
         JR     EXIT    ; All TBUF zero so exit
STOR1    LD     (1X+0),0 ; Clear DRBUF element
         LD     HL,(COUNT) ; Get current count value
         INC    HL      ; Advance it
         LD     A,H     ; See if over or at 512 bytes
         CP     1       ;
         JP     NC,OVRFW ; Yes then overflow
         LD     (COUNT),HL ; Put back advanced count
         LD     DE,(CUROW) ; Get current row pointer in DE
         LD     HL,TBUF  ; Get TBUF pointer in HL
         LD     BC,0006  ; Count for six motors
         LDIR   ; Copy TBUF to ARST(1)
         LD     (CUROW),DE ; Replace updated row pointer CURCW
EXIT     CALL   CTBUF    ; Clear buffers
         POP    HL      ; *
         POP    BC      ; * Restore Registers
OVRFW   RET         ; Now return to caller
         LD     HL,OVRMS ; Print overflow situation
         CALL  PSTR     ; Message
         CALL  GCHRA    ; Get response
         CALL  PNEWL    ; Print a new line
         CP     'D'     ; User typed a 'D'
         JP     Z,REDO   ; Yes then clear all
         CP     'S'     ; User typed an 'S'
         JR     Z,EXIT2  ; Yes exit with sequence saved
         JR     OVRFW    ; Bad input, try again
REDO    CALL   JNIT     ; Clear all arrays etc
EXIT2   POP    HL      ; *
         POP    BC      ; * Restore Registers
         POP    BC      ; Throw away return address
         JP     QUES1   ; Back to main loop
  
```

SUBROUTINE RESET

; This subroutine clears the POSAR array

```
RESET    PUSH    BC          ; *
         PUSH    DE          ; * Save Registers
         PUSH    HL          ; *
         LD     HL,POSAR     ; Point to POSAR start
         LD     DE,POSAR+1   ; Point to next element
         LD     (HL),00      ; Clear first POSAR element
         LE     BC,11        ; Eleven more row counts to clear
         LDIR                    ; Clear POSAR array
         LD     HL,STRST     ; Print "ARM RESET" message
         CALL  PSTR          ; and
         POP    HL           ; *
         POP    DE           ; * Restore Registers and
         POP    BC           ; *
         RET                    ; Return to caller
```



## INPUT/OUTPUT ROUTINES

; PUTCHR prints a character in A

```

PUTCHR      PUSH   AF      ; Save AF
            PUSH   DE      ; Save DE
            CALL   PCHR    ; Print character in A
            POP    DE      ; Restore DE
            POP    AF      ; Restore AF
            RET                    ; Done, Exit
    
```

; PSTR prints a string pointed to by HL

```

PSTR       PUSH   BC      ; * Save registers that are
            PUSH   DE      ; * corrupted by the TRS80
            CALL   PUTSTR  ; Print the string
            POP    DE      ; * Restore Registers
            POP    BC      ;
            RET                    ; Done, Exit
    
```

: PSPAC prints a space character

```

PSPAC      PUSH   AF      ; Save AF
            LD     A,20    ; A = Space character
            CALL   PUTCHR  ; Print it
            POP    AF      ; Restore AF
            RET                    ; Done, Exit
    
```

; PNEWL prints a new line to the screen

```

PNEWL      PUSH   AF      ; Save AF
            LD     A,0DH   ; A = Newline character
            CALL   PUTCHR  ; Print it
            POP    AF      ; Restore AF
            RET                    ; Done, Exit
    
```

: SCKBD Scans the keyboard once and returns, non  
; zero if character found

```

SCKBD      PUSH   DE      ; Save DE
            CALL   KBI    ; See if character is there
            POP    DE      ; Restore
            RET                    ; Done, Exit
    
```

; GCHRA gets a character from keyboard and displays it

```

GCHRA      CALL   GCHR    ; Get a character
            CALL   PUTCHR  ; Print it
            RET                    ; Done, Exit
    
```

CLEAR SCREEN ROUTINE

; Simple scrolling type screen clear

CLRSC	PUSH	BC	; Save used register
	LD	B,16	; Get screen row count
UPLRW	CALL	PNEWL	; Print a new line
	DJNZ	UPLRW	; Do 16 times
	POP	BC	; Restore Register
	RET		; Exit

DELAY ROUTINES

				; Delay for $10 * E + 10 M$ cycles
DELSW	PUSH	BC		; Save BC
DELS1	PUSH	BC		; Delay for 11 T state
	NOP			; 4 T state delay
	NOP			; 4 T state delay
	POP	BC		; Delay for 11 T states
	DJNZ	DELS1		; Do delay times value in B
	POP	BC		; Restore BC
	RET			; Exit
DELS	PUSH	BC		; Save BC
	LD	B,20		; Set B for 0.001 sec delay (apx)
	CALL	DELSW		; Do delay
	POP	BC		; Restore EC
	RET			; Exit
DELT	PUSH	BC		; Save BC
	LD	E,0		; Set B for 0.01 sec delay (apx)
	CALL	DELSW		; Dc delay
	POP	BC		; Restore BC
	RET			; Exit
DELLN	PUSH	EC		; Save BC
	LD	B,200		; Set B for 1.0 sec delay (apx)
DDDD	CALL	DELSW		; Do delay
	DJNZ	DDDD		; Do next delay section
	POP	BC		; Restore BC
	RET			; Exit



FULL STEPPING AND HALF STEPPING THE MOTORS

Two tables are shown below, the first indicates the sequence for full stepping the motors and the second table shows the pulse pattern for half stepping the motors.

FULL STEPPING SEQUENCE

<u>QA</u>	<u>QB</u>	<u>QC</u>	<u>QD</u>	<u>STEP</u>
1	∅	1	∅	1
1	∅	∅	1	2
∅	1	∅	1	3
∅	1	1	∅	4

HALF STEPPING PULSE SEQUENCE

<u>QA</u>	<u>QB</u>	<u>QC</u>	<u>QD</u>	<u>STEP</u>
1	∅	1	∅	1
1	∅	∅	∅	1.5
1	∅	∅	1	2
∅	∅	∅	1	2.5
∅	1	∅	1	3.∅
∅	1	∅	∅	3.5
∅	1	1	∅	4
∅	∅	1	∅	4.5

The documental program contains a table FTABL which is shown below. This table contains the step sequence for full stepping also shown below is the new table FTABLH which contains the sequence for half stepping. To use this table (FTABLH) in the program it will be necessary to alter a few lines of code in the DRAMT routine. The comparison with 5 CPI 5 should be changed to a comparison with 9 and the program line LD A,4 should be changed to LD A,8. The table FTABL should now be changed so it appears as FTABLH

FULL STEP TABLE

			Step number
FTABL	DEFB	192	1
	DEFB	144	2
	DEFB	48	3
	DEFB	96	4

HALF STEP TABLE

			Step number
FTABLH	DEFB	192	1
	DEFB	128	1.5
	DEFB	144	2
	DEFB	16	2.5
	DEFB	48	3
	DEFB	32	3.5
	DEFB	96	4
	DEFB	64	4.5

If you compare the table values with the tables on the previous page you will note a difference, this is because QB and QC are exchanged in the above table due to the hardware switching these two lines.

NOTE

REMEMBER WHEN WRITING PROGRAMS DIRECTLY DRIVE THE ARM SO THAT THE QB AND QC OUTPUT BITS SHOULD BE REVERSED, SO THAT THE TOP FOUR BITS ARE:-

D8 = QA  
D7 = QC  
D6 = QB  
D5 = QD

S E C T I O N 2

C

O

M

M

A

N

D

R

O

U

T

I

N

E

S



## COMMAND INDEX

STARM..... Program entry point  
LEARN..... Learn a sequence command  
EDIT..... Edit a sequence command  
READ..... Read in sequence from tape command  
WRITE..... Write sequence to tape command  
CHECK..... Check stored sequence command  
BOOT..... Re-start system command  
FINSH..... Exit from system command  
SETARM..... Set start position command  
TOSTM..... Move arm to start position command  
FREARM ..... Free all arm joints  
MANU..... Go into manual mode  
GO ..... Execute stored sequence command  
DISPLAY..... Display stored Sequence command

MAIN LOOP

; Program start

```

STARM      CALL CLRSC      ; Clear the TRS80 Screen
           LD HL,SIGON    ; Point to sign on message
           CALL PSTR      ; Print it
           CALL PNEWL     ; Print a new line
           CALL INIT      ; Set up system
QUES1      CALL DELT      ; Small delay
           LD HL,QUESS    ; Point to menue string
           CALL PSTR      ; Print it
           CALL GCHRA     ; Get response and print it
           CALL PNEWL     ; Print new line
           CP NL          ; Is response a newline
           JR Z,QUES1     ; Yes then ignore
           CP 'L'        ; Is response an 'L'
           JP Z,LEARN     ; Yes do learn section
           CP 'E'        ; Is it an 'E'
           JP Z,EDIT      ; Yes do edit
           CP 'R'        ; Is it an 'R'
           JP Z,READ      ; Yes then do read command
           CP 'W'        ; Is it a 'W'
           JP Z,WRITE     ; Yes do write command
           CP 'C'        ; Is it a 'C'
           JP Z,CHECK     ; Yes do check routine
           CP 'S'        ; Is it an 'S'
           JP Z,SETAM     ; Yes then do arm set
           CP 'T'        ; a 'T'
           JP Z,TOSTM     ; Yes then move arm to start
           CP 'G'        ; a 'G'
           JP Z,GO        ; Do execute movements stored
           CP 'D'        ; a 'D'
           JP Z,DISP     ; Yes then display ARST array
           CP 'B'        ; a 'B'
           JP Z,BOOT     ; Yes then restart system
           CP 'M'        ; an 'M'
           JP Z,MANU     ; Yes the Manual control of arm
           CP 'F'        ; a 'P'
           JP Z,FREARM   ; Yes then clear all motors
           CP 'Q'        ; a 'Q'
           JP Z,FINSH    ; Yes then quit program
           LD HL,QMESS    ; Point to 'PARDON' message
           CALL PSTR      ; Print it
           JP QUES1      ; Try for next command

```

THE LEARN ROUTINE

; This section deals with the recording  
; of an arm sequence

```

LEARN      LD      HL,RELNS ; Point to learn message
           CALL   PSTR      ; Print the message
           CALL   GCHRA     ; Get response and print it
           CALL   PNEWL     ; Print a new line
           CP     '.'       ; Response a '.'
           JP     Z,QUES1   ; Back to main loop is uder types a '.'
           CP     'S'      ; Response an 'S'
           JR     Z,WAIT1   ; Learn sequence from start
           CP     'C'      ; a 'C'
           JR     Z,NOINT   ; Continue learning from end of
                           ; sequence
           CALL   PNEWL     ; output a new line
           JR     LEARN     ; Bad answer so try again
WAIT1      CALL   MOVTO     ; Move arm to start position
           CALL   INIT      ; Clear variables
WAIT2      LD      HL,CASRD ; Point to waiting message
           CALL   PSTR      ; Print it
           CALL   GCHRA     ; Get response and print it
           CALL   PNEWL     ; Print new line character
           CP     '.'       ; Response a '.'
           JP     QUES1     ; Exit to main loop if so
           CP     SPAC      ; Is it a space?
           JR     NZ,WAIT2  ; If not then bad input, try again
           CALL   TORQUE    ; Switch motors on
           JR     STLRN     ; Do rest of learn
NOINT      LD      HL,(COUNT); Get current count
           LD      A,L      ;
           OR     H         ; Is it zero?
           JR     Z,NOSTR   ; Yes then can't add to nothing
STLRN      XOR     A        ; Clear manual flag
           LD     (MAN)A    ; Because we are in learn mode
CONLN      CALL   KEYIN     ; Drive motors and store sequence
           OR     A         ; Zero key pressed
           JR     NZ,CONLN  ; No then continue
           CALL   MOVTO     ; Move arm to start position
           JP     QUES1     ; Back to main loop

```



EDIT FUNCTION

```

EDIT      LD      HL,(COUNT) ; Get row count
          LD      A,L          ;
          OR      H            ; Test for zero
          JP      Z,NOSTR     ; Yes then nothing in store
EDSRT     LD      HL,ECOMS    ; Print edit message
          CALL    PSTR        ;
          CALL    GCHRA       ; Get response
          CALL    PNEWL       ; Print a new line
          CP      'M'         ; Is response an 'M'
          JR      Z,EDMOT     ; Yes then edit motor
          CP      'R'         ; Is response an 'R'
          JR      NZ,EDSRT    ; No then try again
          LD      HL,COUITS   ; HL = New row count message
          CALL    PSTR        ; Print it
          CALL    GINT        ; Get 16 bit signed integer
          JP      NZ,BADC     ; Non zero return means bad input
          LD      A,H         ; Test top bit of HC
          BIT     7,A         ;
          JP      NZ,BADC     ; If negative then bad input
          LD      BC,(COUNT) ; Get count value
          PUSH   HL          ; Save response
          OR     A           ; Clear carry flag
          SBC   HL,BC       ; See if response < current count
          POP    HL         ; Restore response
          JR    NC,BADC     ;
          LD    (COUNT),HL ; Replace count with response
          JP    QUES1       ; Back to main loop
EDMOT     LD      HL,EDSTR    ;
          CALL   PSTR        ; Print 'row number'
          CALL   GINT        ; Get integer response
          JR    NZ,BADC     ; Bad answer
          LD    A,H         ;
          BIT   7,A         ; No negative row count
          JR    NZ,BADC     ; allowed
          LD    A,H         ;
          OR    L           ; or zero row count
          JR    Z,BADC      ;
          LD    BC,(COUNT) ; Get row count into BC
          INC   BC         ; Move count up one
          PUSH  HL         ; Clear carry flag
          SBC  HL,BC       ; Subtract count from response
          POP   HL         ; Restore response
          JR   NC,BADC     ; If greater than allowed error
EDOK      DEC    HL        ; Move response down one
          ADD   HL,HL       ; Double HL
          PUSH  HL         ; Save it
          ADD   HL,HL       ; Row count x 4
          POP   BC         ; BC = row count x 2

```

```

ADD      HL,BC      ; HL = Row count x 6
LD       BC,ARST   ; Get store start address
ADD      HL,BC      ; Add row offset
PUSH     HL         ; Save resulting pointer
LD       HL,MOTNS  ; Print
CALL     PSTR      ; Motor number string
CALL     GINT      ; Get Answer
JR       NZ,BADNM  ; Bad answer
LD       A,H       ;
OR       A         ;
JR       NZ,BADNM  ; Response too large
LD       A,L       ;
CP       1         ;
JR       C,BADUM   ; No motor number < 1
CP       7         ;
JR       NC,BADNM  ; No motor number > 6
POP      HL        ; Restore = Memory pointer
DEC      A         ; Motor offset 0 → 5
LD       C,A       ;
LD       B,0       ; Add to memory pointer
ADD      HL,BC     ; Now we point to motor in store
PUSH     HL        ; Save pointer
LD       HL,NVALS  ;
CALL     PSTR      ; Print new step value
CALL     GINT      ; Get response
JR       NZ,BADNM  ; Bad answer
LD       A,H       ;
CP       0FFH     ;
JR       NZ,PEDIT  ; We have a positive response
BIT      7,L       ; New negative step value too
JR       Z,BADNM   ; large
JR       MOTAS     ; Step value OK
PEDIT    OR        A ; New positive step value too
JR       NZ,BADNM  ; large
BIT      7,L       ; so exit
JR       NZ,BADNM  ; else ok
MOTAS    LD        A,L ; Get step value
POP      HL        ; Restore memory pointer
LD       (HL),A    ; Place step value in store
JP       QUES1     ; Go do next operation
BADNM    POP      HL ;
BADC     LD        HL,BADMS ; Print error message and
CALL     PSTR      ;
JP       QUES1     ; return to main loop

```



READ ROUTINE

; Reads stored sequence from cassette  
 ; into memory

```

READ  LD      HL,CASRD  ; Point to wait message
      CALL   PSTR      ; Print it
      CALL   GCHRA     ; Get response
      CALL   PNEWL     ; Print new line
      CP     '.'       ; Is response a dot?
      JP     Z,QUES1   ; Yes then exit
      CP     SPAC      ; Is it a space?
      JR     NZ,READ   ; No then try again
      XOR    A         ; Clear A=Drive zero
      CALL   CASON     ; Switch on drive zero
      CALL   DELS      ; Short delay
      CALL   RDHDR     ; Read header from tape
      CALL   READC     ; Read first character
      LD     B,A       ; Put in B
      CALL   READC     ; Read second character
      LD     C,A       ; Place in C
      OR     B         ; BC now equals count
      JP     Z,NOSTR   ; Count zero, so exit
      LD     (COUNT),BC ; Set count = read count
      LD     HL,ARST   ; Point to start of store
ROWNR  PUSH   BC       ; Same count
      LD     E,Ø       ; E = Check sum for a row
      LD     B,6       ; B = Column Count
RDBYT  CALL   READC     ; Read a row element
      LD     (HL),A    ; Store it
      ADD   A,E        ; Add it to check sum
      LD     E,A       ; Store in check sum
      INC  HL         ; Inc memory pointer
      DJNZ RDBYT      ; Do next element
      POP  BC         ; Restore row count
      CALL  READC     ; Read check digit
      CP   E         ; Same as calculated?
      JR   NZ,RDERR  ; No then error
      DEC  BC         ; Decrement row count
      LD  A,B        ; See if row count
      OR  C          ; is zero
      JR  NZ,ROWNR  ; No then read next row
      CALL CASOF    ; Switch cassette off
      JP  TAPEF     ; exit
RDERR  LD  HL,RDMSG  ; Error message for tape
      CALL PSTR      ; Print it
      JP  QUES1     ; Go to main loop
  
```



WRITE ROUTINE

; Writes a stored sequence to tape

WRITE	LD	BC, (COUNT)	; Get row count
	LD	A,B	;
	OR	C	;
BADWI	JP	Z,NOSTR	; If zero exit
	LD	HL,CASRD	; print message
	CALL	PSTR	;
	CALL	GCHRA	; Get answer
	CALL	PNEWL	; Print new line
	CP	'.'	; Is answer a dot
	JP	Z,QUES1	; Yes then exit
	CP	SPAC	; Is answer a space
	JR	NZ,BADWI	; No then try again
	XOR	A	; Clear drive number
	CALL	CASON	; Switch on drive zero
	CALL	DELT	; delay
	CALL	WRLDR	; Write Leader
	CALL	DELT	; delay
	LD	BC, (COUNT)	; Get count into BC
	LD	A,B	;
	CALL	WRBYA	; Write higher byte
	LD	A,C	; Get lower byte of count into A
	CALL	DELT	; delay
	CALL	WRBYA	; Write lower byte
ROWNW	LD	HL,ARST	; Point to start of sequence of store
	PUSH	BC	; Save row count
	LD	E,Ø	; Clear check sum
	LD	B,6	; Six motor slots per row
WRBYT	LD	A, (HL)	; Get motor slot N
	CALL	DELS	; delay
	CALL	WRBYA	; Write it
	CALL	DELS	; delay
	ADD	A,E	; add to check sum
	LD	E,A	;
	INC	HL	; Inc memory pointer
	DJNZ	WRBYT	; Do for all six motors
	CALL	WRBYA	; Write check sum
	POP	BC	; Restore row count
	DEC	BC	; Decrement row count
	LD	A,B	;
	OR	C	; Test if zero
	JR	NZ,ROWNW	; No then try again
	CALL	CASOF	; Switch cassette off
	JP	QUES1	; Back to main loop

## CHECK ROUTINE

; Checks tape with sequence in store

CHECK	LD	BC, (COUNT)	; Get row count
	LD	A, B	;
	OR	C	;
	JP	Z, NOSTR	; If zero exit
BADCI	LD	HL, CASRD	; Print wait message
	CALL	PSTR	;
	CALL	GCHRA	; Get answer
	CALL	PNEWL	; Print new line
	CP	'.'	; Is response a '.'
	JP	Z, QUES1	; Yes then go to main loop
	CP	SPAC	; Is it a space
	JR	NZ, BADCI	; No then try again
	XOR	A	; Clear cassette number
	CALL	CASON	; Switch drive zero on
	CALL	RDHDR	; Read header from tape
	LD	BC, (COUNT)	; Get row count
	CALL	READC	; Read first section
	CP	B	; Same?
	JR	NZ, RDERR	; No then error
	CALL	READC	; Read lower byte of count
	CP	C	; Same?
	JR	NZ, RDERR	; No then error
	OR	B	; Zero count from tape
	JP	Z, NOSTR	; So exit
	LD	HL, ARST	; Point to start of memory
ROWNC	PUSH	BC	; Save count
	LD	E, 0	; Check sum is zero
	LD	B, 6	; Count is 6
CKBYT	CALL	READC	; Read a motor step element
	CP	(HL)	; Same as in store?
	JP	NZ, RDERR	; Not the same so error
	ADD	A, E	;
	LD	E, A	; Add to check sum
	INC	HL	; Advance memory pointer
	DJNZ	CKBYT	; Do next row element
	POP	BC	; Restore row count
	CALL	READC	; Read check sum
	CP	E	; Same as check sum calculated
	JP	NZ, RDERR	; No then error
	DEC	BC	; Decrement count
	LD	A, B	;
	OR	C	; Is count zero?
	JP	NZ, ROWNC	; No then do next row
	CALL	CASOF	; Switch cassette off
TAPEF	LD	HL, TAPOK	; Print tape off message
	CALL	PSTR	;
	JP	QUES1	; and back to main loop

BOOT AND FINISH COMMANDS

; This routine restarts the program

```

BOCT      LD      HL,BOOTS      ; Print "DO YOU REALLY
          CALL    PSTR          ; WANT TO RESTART?"
          CALL    GCHRA         ; Get answer
          CP      'Y'          ; User typed 'Y'?
          JP      Z,STARM       ; Yes then restart program
          CP      'N'          ; No 'N'?
          JR      NZ,BOCT       ; Then try again
          CALL    PNEWL         ; else print new line and
          JP      QUES1         ; back to main loop
    
```

; This is the exit from program Section to TRS80  
; system level

```

FINSH     LD      HL,RELYQ      ; Print "REALLY QUIT"
          CALL    PSTR          ;
          CALL    GCHRA         ; Get answer
          CP      'Y'          ; User typed a 'Y'
          JR      NZ,TRYNO      ; No then try 'N'
          LD      HL,SIGOF      ; Print ending message
          CALL    PSTR          ; and then
          JF      FINAD         ; return to TRS80 System
TRYNO     CP      'N'          ; User typed an 'N'
          JR      NZ,FINSH      ; No then try again
          CALL    PNEWL         ; Print a new line
          JP      QUES1         ; Back to main loop
    
```



#### OTHER SHORT COMMANDS

; SETAM: clears arm position array

```
SETAM    CALL    RESET    ; Clear Arm array  (POSAR)
         JP      QUES1    ; Back to main loop
```

; TOSTM moves the arm back to its start position

```
TCSTM    CALL    MOVTO    ; Steps motors till POSAR elements
         JP      QUES1    ; are zero then back to main loop
```

; FREARM frees all motors for user to move arm  
; by hand

```
FREARM   CALL    CLRMT    ; Output all ones to motors
         JP      QUES1    ; and now to main loop
```

; MANU allows the user to move the arm using  
; the 1-6 keys and the 'Q' 'W' 'E' 'R' 'T' 'Y' keys  
; The movements made are not stored.

```
MANU     LD      A,1      ; Set in manual mode for the
         LD      (MAN),A ; keyin routine
MANUA    CALL    KEYIN    ; Now get keys and move motors
         JP      NZ,MANUA; If non zero then move to be done
         XOR     A        ; Clear manual flag
         LD      (MAN),A ;
         JP      QUES1    ; Back to main loop
```

## THE GO COMMAND

```

; This command causes the computer to step
; through a stored sequence and makes the arm
; follow the steps stored, if the sequence is to
; be done fcrever then the arm resets itself at
; the end of each cycle.

GO      CALL      PNEWL      ; Print a new line
        CALL      MOVTO      ; Move arm to start
        XOR       A          ; Clear
        LD        (FORFG),A  ; Forever Flag FCFEG
        LD        HL,AORNM   ; Print "DO ONCE OR FCREVER
        CALL      PSTR       ; Message
        CALL      GCHRA      ; Get answer and print it
        CALL      PNEWL      ; Print a new line
        CP        'O'        ; User typed an 'O'
        JR        Z,ONECY    ; Do sequence till end
        CP        'F'        ; User typed an 'F'
        JF        NZ,GO      ; No then re-try
        LD        A,1        ; Set fcrever flag
        LD        (FORFG),A  ; to 1
ONECY   LD        A, '.'      ; Print a '.'
        CALL      PUTCHR     ; Using PUTCHR
        CALL      DCALL      ; Execute the sequence
        LD        A,(FORFG)  ; Test FORFG, if zero
        OR        A          ; then we do not want
        JF        Z,NCRET    ; to carry on so exit
        CALL      DELT       ; delay
        CALL      MOVTO      ; Move arm to start
        CALL      DELLN      ; Delay approx 1 second
        JR        ONECY      ; Do next sequence
NCRET   LD        HL,DONMS   ; Print sequence done
        CALL      PSTR       ;
        JP        QUES1      ; and go to main loop

```

## THE DISPLAY COMMAND

```
; This command allows the user to display
; the motor sequence so that he can then
; alter the contents of a sequence by using
; the edit command
```

```
DISP      LD      HL,DISPS      ; Point to header string
          CALL    PSTR          ; and display it
          CALL    POSDS        ; Print out the relative position
          LD      HL,ARST      ; Point to sequence start
          LD      BC,(COUNT)  ; BC = how many rows to print
          LD      A,B          ;
          OR      C            ; Test if count is zero
          JP      NZ,SETBC     ; No then jump to rest of
NOSTR     LD      HL,NODIS     ; display else print message
          CALL    PSTR          ; telling user no display and
          JP      QUES1        ; return to the main loop
SETBC     LD      EC,0000      ; Clear BC for row count
DORCW    PUSH    EC            ; Save it
          PUSH    HL           ; Save memory position
          LD      H,B          ;
          LD      L,C          ; HL = row count
          INC     HL           ; Now row count =N+1
          LC      LX,NUMAR     ; LX points to buffer for ASCII String
          CALL    CBTAS        ; Convert HL to ASCII
          LC      HL,NUMAR     ; Point to ASCII string
          CALL    PSTR          ; now print it
          LD      A,'.'        ;
          CALL    PUTCHR        ; Print a '.'
          POP     HL           ; Restore memory pointer
          LD      B,6          ; Motor count to B (6 motors)
NEXTE    LD      A,(HL)        ; Get step value
          PUSH    HL           ; Save memory pointer
          PUSH    BC           ; Save motor count
          EJT     7,A          ; Test bit 7 of A for sign
          JR      Z,NUMPO      ; If bit = 0 then positive step
          LD      H,0FFH       ; Make H = negative number
          JR      EVAL         ; Do rest
NUMPO    LD      E,0           ; Clear E for positive number
EVAL     LD      L,A           ; Get low order byte into L
          LD      LX,NUMAR     ; Point to result string
          CALL    CBTAS        ; Call conversion routine
          LD      HL,NUMAR     ; HL points to result
          CALL    PSTR          ; Print resulting conversion
          LD      A,(3810H)     ; Get keyboard memory location
          BIT     0,A          ; Test for zero key pressed
          JR      Z,NOSTP      ; Not pressed, then skip
DOSTF    CALL    GCHR          ; Wait till next character entered
          CP      '.'          ; Is it a dot?
          JR      NZ,NOSTP     ; No then carry on
          CALL    PNEWL        ; else print a new line
          POP     BC           ; and restore all the registers
          POP     HL           ; and the stack level
```



NOSTP

```
POP      BC      ;
JP       QUES1   ; Jump back to main loop
POP      BC      ; Restore column count
POP      HL      ; Restore memory pointer
INC      HL      ; Increment memory pointer
CALL     PSPAC   ; Print a space between
           ; numbers
DJNZ     NEXTE   ; Do for six motors
CALL     PNEWL   ; Print a new line
POP      BC      ; Restore row count
INC      BC      ; Increment row count
LD       A,(COUNT) ; Get lower count byte
CP       C       ; Is it the same
JR       NZ,DOROW ; No then do next row
LD       A,(COUNT+1) ; Get higher order count byte
CP       B       ; Same?
JR       NZ,DOROW ; No then do next row else
CALL     PNEWL   ; print a new line and then
JP       QUES1   ; back to main loop
```

## SUBROUTINES INDEX

DOALL.....Execute a stored sequence once  
DRIVL.....Drives all motors directed by TBUF  
INIT.....Set up system  
MOVTO.....Use PCSAR to rest system arm  
TORQUE.....Turn on off motors  
CLRMT.....Turn off all motors  
SETCT.....Reset CTPOS elements to one  
DRAMT.....Drive directed motors  
STEPM.....Step motors via DRAMT  
DNEWB.....Delay on direction change  
SPAMT.....Update TBUF array during learn  
KEYIN.....Scan keyboard and build up motors to move  
CBTAS.....Convert 16 bit 2's complement number to ASCII  
CLRMP.....Clear MOTBF array  
CTBUF.....Clear TBUF, DRBUF & MOTBF arrays  
GINI.....Get 16 bit signed value from keyboard  
POSDS.....Display relative position array elements  
POSJC.....Increment relative position array elements  
STORE.....Copy TBUF to current ARST slice  
RESET.....Clear POSAR array  
PUTCHR.....Print a character  
PSTR.....Print a string  
PSPAC.....Print a space  
PNEWL.....Print a carriage return

S E C T I O N 3

S  
U  
B  
R  
O  
U  
T  
I  
N  
E  
S.



SUBROUTINES INDEX (continued)

SCKBE.....Scan the keyboard  
GCHPA.....Get a character and print it  
CLRSC.....Clear the Screen  
DELSW.....Delay on value in B  
DELS.....Delay approx 0.001 sec  
DELT.....Delay approx 0. 01 sec  
DELLN.....Dealy approx 1. 0 sec

SUBROUTINE DOALL

; This subroutine executes a sequence in store cnce.  
 ; Forever flag FORFG is cleared if user types a '.'

DOALL	LD	BC,(COUNT)	; Get sequence row count.
	LD	A,B	;
	OR	C	; If count zero then
	JR	Z,RET2	; exit
	LD	HL,ARST	; HL points to memory start
NMOTS	LD	DE,TBUF	; DE points to temporary buffer
	PUSH	BC	; Save count
	LD	EC,0006	; Motor count of six
	LFIR		; Copy memory slice into TBUF
	PUSH	HL	; Save new memory pointer
	CALL	DRIVL	; Drive all motors for this slice
	CALL	SCKBD	; See if keyboard input
	POP	HL	; Restore memory pointer
	POP	BC	; Restore row count
	CALL	DNEWB	;
	CP	'.'	; User typed a '.'
	JR	NZ,CARON	; No then continue
RET2	XOR	A	; Clear A
	LD	(FORFG),A	; Clear flag to halt routine above
	RET		; exit
CARON	DEC	BC	; Decrement count
	LD	A,B	;
	OR	C	; Test for zero
	JR	NZ,NMOTS	; No then carry on else
	RET		; return

SUPERROUTINE DRIVL

; This routine is given TBUF, it then drives all  
 ; the motors that need to be driven, till TBUF = 0

```

DRIVL      LD      C,0      ;
SCANW     LD      E,6      ; Set BC = motor count
          LD      HL,TBUF   ; Point to TBUF
TBZER     LD      A,(HL)    ; Get step value from TBUF
          OR      A        ; Is it zero?
          JR      NZ,TBNZR  ; No then continue
          INC     HL       ; Point to next TBUF location
          DJNZ   TBZER     ; Do next motor check
          RET      ; If no motor to step, then return
TBNZR     LD      DE,MOTBF + 5 ; DE points to last direction array
          LD      HL,TBUF + 5 ; HL points to TBUF
          LD      B,6      ; B = motor count
DOAGN     LD      A,(HL)    ; Get motor step value
          CP      0        ; Is it zero?
          JR      Z,NOEL    ; Yes then skip
          JP      M,SNeg    ; Is it negative ie, reverse
SPOS      LD      A,3      ; No positive, so load MOTBF (N)
          LD      (DE),A    ; With 3
          DEC     (HL)     ; Decrement motor count in TBUF
          JR      NOFIL    ; Complete the MOTBF array
SNeg      LD      A,1      ; Set MOTBF = 1 for
          LD      (DE),A    ; a positive drive
          INC     (HL)     ; Decrement negative count
          JR      NOFIL    ; Do rest of MOTBF
NOEL      XOR     A        ; Clear MOTBF (N)
          LD      (DE),A    ;
NOFIL     DEC     DE       ; Move to next MOTBF element
          DEC     HL       ; Move to next TBUF element
          DJNZ   DOAGN    ; Do for all six motors
          LD      A,1      ;
          LD      (KEYP),A  ; Set key pressed flag
          CALL   STEPM     ; Step all motors once if
          DEC     C        ; any to step
          JF     NZ,SCANW  ; Do for maximum of 128 cycles
          RET      ; then return
  
```



SUBROUTINE INIT

; INIT clears the row count (COUNT), resets the  
; MAN flag, clears the TBUF, DRBUF, & MOTBF arrays  
; The CUROW pointer is reset to the start of the ARST,  
; position array is cleared.

```
INIT      LD      HL,Ø      ; Set HL = Ø
          LD      (COUNT),HL ; and clear the row count
          XOR     A          ; Clear A
          LD      (MAN),A    ; Now clear MAN
          LD      HL,ARST   ; HL = start of arm store
          LD      (CURCW),HL ; CUROW = start of arm store
          CALL    CTBUF     ; Clear TBUF, DRBUF & MOTBF
          CALL    RESET    ; Clear the POSAR array
          CALL    CLFMT    ; Free all motors
          RET              ; EXIT
```

SUBROUTINE MOVIC

; This routine takes the POSAR array and uses it to drive  
 ; all the motors until the ARM is in its defined start position

```

MOVTO    PUSH    AF          ; *
         PUSH    BC          ; *
         PUSH    LE          ; *   Save registers
         PUSH    HL          ; *
RES1     LD     HL,POSAR     ; HL points to POSAR
         LD     B,12         ; B = count of 12
NRES1    LD     A,(HL)       ; Get FCSAR element
         OR     A            ; Is it zero?
         JR     NZ,MTSA      ; No then continue
         INC    HL           ; Point to next POSAR element
         DJNZ  NRES1        ; See if all zero
         JR     ENDDC        ; All zero so end!
MTSA     LD     HL,FCSAR+10  ; HL points to POSAR
         LE    DE,MOTBF+ 5  ; DE points to MOTBF
         LE    B,6          ; B = count
RSCAN   PUSH    BC          ; Save count
         LD     C,(HL)       ; Get lower byte
         INC    HL           ; Advance HL pointer
         LD     B,(HL)       ; Get high byte of POSAR element
         LD     A,C          ; Get low byte into A
         OR     B            ; See if POSAR(N) is zero
         JP     NZ,DOMPL     ; no skip
         LD     (DE),A       ; Zero MOTBF (N)
         DEC    HL           ; advance POSAR pointer
         JR     NMDR         ; Do next motor
DOMFL   LD     A,B           ; See direction to move in
         BIT    7,A          ;
         JR     Z,RMOT1     ; Go in reverse
         INC    BC           ; Go forward
         LD     A,1          ; A = forward
         JR     DOIT1       ; Do rest
RMOT1   DEC    EC           ; Dec count for reverse
         LD     A,3          ; Set reverse in A
DOIT1   LD     (DE),A       ; Store reverse in MOTBF (N)
         LD     (HL),B       ; Store updated POSAR count
         DEC    HL           ; in POSAR (N)
         LD     (HL),C       ; Store lower byte
NMDR    DEC    HL           ;
         DEC    HL           ; point to next POSAR element
         DEC    DE           ; Move to next MOTBF element
         POP    BC           ; Restore motor count
         DJNZ  RSCAN        ; Do for next motor
         CALL  DRAMT        ; Drive all motors to be driven
         JR     RES1        ; Do till all POSAR slots zero
ENDDC   POP    HL           ; *
         POP    DE           ; *
         POP    BC           ; *   Restore all registers
         POP    AF          ; *
         RET                ; Return

```

SUBROUTINES TORQUE, CLRMT AND SETDT

; TORQUE switches of motors on and sets CTPOS(N)'s  
 ; CLRMT turns all motors off and sets CTPCS(1-6)  
 ; SETDT sets all CTPOS elements to start offset  
 ; position which equals 1.

```

TORQUE    PUSH    AF      ; * Set clear motor-
          PUSH    BC      ; *
          PUSH    DE      ; * Save Registers
          PUSH    HL      ; *
          LD     HL,TORMS ; Print TORQUE ON message
          CALL   PSTR     ;
          LD     DE,CTPOS ; Point to FTABL offset array
          LD     HL,MOTBF ; Point to last drive table
          LD     B,6      ; B = motor count
TORQ1     LD     A,(HL)   ; Get motor value
          OR     A        ; Is it zero?
          JR     NZ,TORQ2 ; No then skip
          LD     A,1      ; Reset CTPOS(N) to position 1
          LD     (DE),A   ; in FTABL
          LD     A,B      ; Get motor address in A
          SLA   A        ; Shift it left for interface defn
          OR     192     ; or in FTABL pulse
          OUT   (PORT),A ; Output it to selected motor
TORQ2     INC    DE      ; Advance points to next
          INC    HL      ; motors
          DJNZ  TORQ1    ; Do next motor
          JR     TOQCL   ; Exit with register restoration
CLRMT     PUSH    AF      ; * clear all motors torque
          PUSH    BC      ; *
          PUSH    DE      ; * Save Registers
          PUSH    HL      ; *
          LD     HL,NOTOR ; Print "NO TORQUE" message
          CALL   PSTR     ;
          LD     D,ØFØH   ; Pattern for motors off
OTMT      LD     B,6      ; B = Motor count
CLNT      LD     A,B      ; Get motor address in A
          SLA   A        ; Shift into correct bit position
          OR     D        ; Combine with coils off pattern
          OUT   (FORT),A ; Output to selected motor
          DJNZ  CLNT     ; Do next motor
          CALL   SETDT   ; Clear CTPOS array to value of 1
TOQCL     POP    HL      ; *
          POP    DE      ; *
          POP    BC      ; * Restore Registers
          POP    AF      ; *
          RET           ; Done, exit
  
```



```

SETDT    PUSH    BC      ; * Set CTPOS elements to start
          PUSH    DE      ; * Save used registers
          PUSH    HL      ; *
          LD     B,6      ; Motor count to B
          LD     HL,CTPOS ; HL points to CTPOS array
NSET1    LE     (HL),1    ; Set CTPOS(N) to start position = 1
          INC    HL      ; Increment HL
          DJNZ   NSET1   ; Do set up next CTPOS element
          POP    HL      ; *
          POP    DE      ; * Restore used registers
          POP    BC      ; *
          RET           ;

```

SUBROUTINE DRAMT

; DRAMT drives all six motors directly and uses  
 ; FTABL to output the correct pulse patterns.  
 ; For half stepping the pattern must be changed in FTABL  
 ; and the bounds in DRAMT

```

DRAMT      PUSH  AF          ; *
           PUSH  BC          ; *
           FUSH  DE          ; * Save Registers
           PUSH  HL          ; *
           LD    B,6         ; B = motor count
           LD    DE,MOTBF +5 ; Point to MOTBF array
           LD    HL,CTPOS    ; HL points to FTABL offset array
NMTDT      LD    A,(DE)      ; Get MOTEF(N)
           OR    A           ; Is it zero?
           JR    Z,IGMTN    ; If zero, then skip
           BIT   1,A         ; Test direction
           CALL  OUTAM       ; Step motor
           JR    Z,REVMT     ; If direction negative then jump
           INC   A           ; Increment table counter
           CP    5           ; Upper bound?
           JR    C,NORST     ; No then continue
           LD    A,1         ; Reset table offset
NORST      LD    (HL),A      ; Store in CTPOS (N)
IGMTN      INC   HL          ; Increment CTPOS pointer
           DEC   DE          ; Decrement MOTBF pointer
           DJNZ NMTDT        ; Do for next motor
           CALL  DELT        ; Delay after all pulses out
           CALL  DELS        ; *
           POP   HL          ; *
           POP   DE          ; *
           POP   BC          ; * Restore Registers
           POP   AF          ; *
           RET                ; Exit
REVMT      DEC   A           ; Move table pointer on
           CP    1           ; Compare with lower bound
           JR    NC,NORST    ; If no overflow then continue
           LD    A,4         ; Reset table offset
           JR    NORST       ; Do next motor
OUTAM      LD    A,(HL)      ; Get table offset 1-4
           PUSH  AF          ; *
           PUSH  DE          ; * Save Registers
           PUSH  HL          ; *
           LD    HL,FTABL-1  ; Get table start
           LD    D,0         ;
           LD    E,A         ; DE now equals 1-4
           ADD   HL,DE       ; Add to FTABL -1 to get address
           LD    A,(HL)      ; Get motor pulse pattern
           LD    C,B         ; Get address field in C and
           SLA   C           ; shift it one to the left
           OR    C           ; or in the pulse pattern
           CUT   (PCRT),A    ; Output to interface circuitry
           POP   HL          ; *
           POP   DE          ; * Restore Registers
           POP   AF          ; *
           RET                ; Return
  
```

SUBROUTINE STEPM

; This routine causes all motors that should be  
 ; stepped to be so, and updates the motors relative  
 ; positions from their start positions.

```

STEPM      PUSH  AF          ; *
           PUSH  HL          ; * Save Register
           PUSH  BC          ; *
           LD    HL,MOTBF    ; HL points to motor buffer
           LD    B,6         ; B = Ccount
TRYØ       LD    A,(HL)      ; Get motor value 3 or 1
           OR    A           ; Zero?
           JR    NZ,CONTA    ; No then continue
CCNT       INC    HL         ; Point to next motor
           DJNZ  TRYØ        ; Do next motor
           POP   BC          ; *
           POP   HL          ; * Restore Registers
           POP   AF          ; *
           RET              ; Exit
CONTA     PGP   BC          ; *
           POP   HL          ; * Restore registers
           CALL  DRAMT       ; Drive motors
           CALL  POSIC       ; Increment relative position
           PCF   AF          ; * Restore AF
           RET              ; Exit
  
```



SUBROUTINE DNEWD

; This subroutine checks to see if any motors are  
 ; changing direction , if so a delay is inserted  
 ; into the sequence.

```

DNEWD  PUSH  AF          ; *
        PUSH  BC          ; *
        PUSH  DE          ; * save used registers
        PUSH  HL          ; *
        LD    BC,6        ; Load BC with count
        OR    A           ; Clear carry
        SBC   HL,BC       ; HC points to previous motor slice
        LD    D,H         ;
        LD    E,L         ; Move HL to DE
        POP   HL          ; Restore current row pointer
        PUSH  HL          ; Save again
        LD    B,C         ;
NCOMP  LD    A,(HL)       ; Get contents of this row
        CP    Ø           ; See if positive or negative
        LD    A,(DE)      ; Get identical previous motor slot
        JP    P,PDIR      ; if positive do for positive motor
NDIR   CP    Ø           ; Compare if both in same
        JP    M,NXTCK     ; direction then skip else
CDDEL  CALL  DELLN        ; delay and
NCDSG  POP   HL          ; *
        POP   DE          ; *
        POP   BC          ; * Restore registers
        POP   AF          ; *
        RET              ; Now return
PDIR   CP    Ø           ; If previous motor is negative
        JP    P,NXTCK     ; then delay, else do for next
        JR    CDDEL       ; motor slot
NXTCK  INC   HL          ; increment current row pointer
        INC   DE          ; increment lost row pointer
        DJNZ NCOMP        ; do for next motor
        JR    NCDSG       ; Return with no large (1 sec) delay
  
```

SUBROUTINE SRAMT

; SRAMT is responsible for updating the TBUF  
 ; elements and for setting the STRFG if a situation  
 ; exists where the TBUF array should be stored in the  
 ; current ARST slot. This will occur if any motor changes  
 ; direction or a motor exceeds the allowed slct  
 ; boundary of -128 to 127.

```

SRAMT      LD      A,(MAN)      ; Get manual flag
           OR      A            ; Is it zero?
           JP      NZ,STEPM     ; Yes then just step motors
           LD      (STRFG),A    ; Clear the store flag
           LD      B,6          ; B = motor count
           LD      LX,DRBUF+6   ; LX = previous direction buffer
           LD      LY,MOTBF+6   ; LY = current buffer
           LD      HL,TBUF +6   ; HL = step buffer
NTMOT      DEC     LY           ;
           DEC     LX           ;
           DEC     HL           ; move pointers
           LD      A,(LY +0)    ; Get current motor direction
           OR      A            ; No work to do
           JR      Z,NODRV     ; skip, if so
           CP      1           ; Reverse
           JR      Z,REVDR     ; Yes then skip
FORDR      LD      A,(LX+0)    ; Get previous direction
           CP      1           ; Direction change?
           JR      NZ,CFORD    ; No then advance TBUF(N) step
           CALL   SETST       ; Set the store flag
           LD      (LY+0),0    ; Clear MCTEF element.
           JR      NODRV     ; Do next motor
CFORD      INC     (HL)       ; Increment rotor step in TBUF
           LD      A,(HL)     ; Get new value
           CP      127        ; Check against upper board
           CALL   SETST       ; Limit reached then store flag
           LD      (LX+0),3    ; Set previous direction
NODRV      DJNZ   NTMOT      ; Do next motor
           CALL   STEPM       ; Step motors to be driven
           LD      A,(STRFG)   ; Examine store flag
           OR      A            ; Zero?
           JP      NZ,STORE    ; No then do store operation
           RET                ; Exit
REVDR     LD      A,(LX+0)    ; Get previous direction
           CP      3           ; Direction reversed?
           JR      NZ,CREV1    ; No then continue
           CALL   SETST       ; Else set store TBUF in ARST flag
           LD      (LY+0),0    ; clear MCTEF element
           JR      NODRV     ; Do next motor
CREV1     DEC     (HL)       ; Advance step count in TBUF (N)
           LD      A,(HL)     ; Get element
           CP      -128       ; Compare with upper negative bound
           CALL   Z,SETST     ; Limit reached so set store flag
CREVD     LD      (LX+0),1    ; Set Direction
           JR      NODRV     ; Do next motor
SETST     PUSH   AF          ; Save AF
           LD      A,1        ; Set store flag STRFG
SETSC     LD      (STRFG),A   ; to one
           POP    AF          ; Restore AF
           RET                ; Continue
  
```



SUBROUTINE KEYIN

; This routine scans the keyboard checking for  
 ; the keys '1-6' and 'Q' 'W' 'E' 'R' 'T' 'Y' and 'S'  
 ; and Ø. It then drives the motors corresponding  
 ; to the keys pressed. If in learn mode the  
 ; sequence is stored.

```

KEYIN      CALL      CLRMF      ; Clear MOTBF array
           LD        A,(384ØH) ; Get TRS8Ø keyboard byte
           BIT       7,A        ; See if
           JR        Z,IGDEL    ; No space key so skip
           CALL      DELT       ; *
           CALL      DELT       ; * Slow motor driving
IGDEL      XOR       A          ; Clear KEY PRESSED flag
           LD        (KEYP),A   ;
           LD        A,(381ØH) ;
           BIT       Ø,A        ; Is the zero key pressed?
           JR        Z,TRYS     ; No then skip
           JP        NOTNG      ; Go to do nothing
TRYS       LD        A,(38Ø4H) ; See if
           BIT       3,A        ; 'S' key pressed
           LD        A,(381ØH) ; Restore memory value
           JR        Z,TRYN1    ; No then skip
           LD        A,(MAN)    ; See if in manual mode
           CR        A          ;
           CALL      Z,STORE    ; No then store TBUF
           OR        1         ; Set not finished flag
           RET        ; and exit to caller
TRYN1     LD        BC,Ø       ; Clear MOTBF offset in BC
           BIT       1,A        ; See if '1' key is pressed
           JP        Z,TRYN2    ; No then skip else
           CALL      FORMT      ; Set up motor 1 position in MOTBF
TRYN2     INC        BC        ; Increment MOTBF offset
           BIT       2,A        ; See if '2' key pressed
           JP        Z,TRYN3    ; No skip
           CALL      FORMT      ; Set second motor forward
TRYN3     INC        BC        ; Advance offset
           BIT       3,A        ;
           JP        Z,TRYN4    ; See if '3' key pressed, No skip
           CALL      FORMT      ; Set forward direction on Motor 3
TRYN4     INC        BC        ; Increment offset in BC
           BIT       4,A        ; See if key '4' is pressed
           JP        Z,TRYN5    ; No then test key '5'
           CALL      FORMT      ; Do forward direction for Motor 4
TRYN5     INC        BC        ; Advance offset
           BIT       5,A        ; Key '5' pressed
           JP        Z,TRYN6    ; No skip
           CALL      FORMT      ; Do set up for motor 5
TRYN6     INC        BC        ; Advance offset
           BIT       6,A        ; Key '6' pressed
           JP        Z,TRYQT    ; No then try 'Q'
           CALL      FORMT      ; Do for motor 6
  
```



```

TRYQT      LD      BC,0           ; Clear BC offset for motor 1
           LD      A,(3804H)      ; See if 'Q' key pressed
TRYQ       EIT     1,A           ;
           JP      Z,TRYW         ; No then skip
           CALL   BACMT          ; Set motor 1 for backward
TRYW       INC     BC            ; Advance pointer
           BIT    7,A           ; See if 'W' key pressed
           JP      Z,TYRE        ; No skip
           CALL   BACMT          ; Do backward for motor 2
TRYE       INC     BC            ; Advance pointer offset
           LD      A,(3801H)      ; See if
           BIT    5,A           ; 'E' key pressed
           JR      Z,TRYR        ; No skip
           CALL   BACMT          ; Set motor 3 for backward
TRYR       INC     BC            ; Advance pointer offset
           LD      A,(3804H)      ; See if
           BIT    2,A           ; Key 'R' is pressed
           JP      TRYT          ; No skip
           CALL   BACMT          ; Set motor 4 backward
TRYT       INC     BC            ; Advance offset
           BIT    4,A           ; Is key 'T' pressed?
           JP      Z,TRYR        ; No skip
           CALL   BACMT          ; Set motor 5 backward
TRYR       LD      A,(3808H)      ; Is the 'Y' key pressed?
           INC     BC            ; Advance offset
           BIT    1,A           ; No key
           JP      Z,SOMEN       ; 'Y' then skip
           CALL   BACMT          ; Set motor 6 for backward
SOMEN     CALL   SRAMT          ; Step motors, maybe store.
           OR     1             ; Set zero key not pressed flag
           RET                    ; Return to caller
NOTNG     LD      A,(MAN)        ; Zero was pressed so see
           OR     A             ; if in learn mode
           CALL   Z,STORE        ; Yes then store
           XOR    A             ; Set zero flag and
           RET                    ; Return to caller
FORMT     LD      E,3           ; Set for forward direction
           JR      SETMT         ; Do set motor slot in MOTBF
BACMT     LD      E,1           ; Set for reverse direction
SETMT     LD      HL,MOTBF       ; Point to MOTBF
           ADD    HL,BC          ; Add in motor offset
           PUSH   AF            ; Save AF
           LD     A,(HL)         ; Get byte
           OR     A             ; See if zero
           JR      Z,DOMOT       ; Yes then set byte
           XOR    A             ; Clear
           LD     (HL),A         ; byte in MOTBF user wants both
           POP    AF            ; directions clear byte
           RET                    ; Restore AF and return
DOMOT     LD     (HL),E         ; Set byte in MOTBF
           LD     A,1           ; and set
           LD     (KEYP),A       ; key pressed flag
           POP    AF            ; Restore AF
           RET                    ; exit from routine

```

SUBROUTINE CBTAS

; This subroutine makes a signed binary value in  
 ; HL into arm ASCII String and stores the string  
 ; in the locations pointed to by IX

```

CBTAS    PUSH    AF          ; *
         PUSH    HL          ; *
         PUSH    DE          ; *   Save Registers
         PUSH    IX         ; *
         BIT     7,H         ; Test sign of number
         JR     Z,POSNO     ; If zero then positive number
         LD     A,H         ;
         CPL          ; Complement number if negative
         LD     H,A         ;
         LD     A,L         ;
         CPL          ;
         LD     L,A         ;
         INC    HL          ; Now 2's complement negative
         LD     A,MINUS     ; Place minus sign in string
PUTSN    LD     (IX+0),A    ; Pointed to by IX
         INC    IX         ; Advance IX pointer
         JR     CONUM       ; Do rest of conversion
POSNO    LD     A,SPAC     ; Place a space if number positive
         JR     PUTSN      ; Jump to copy space to memory
CONUM    PUSH    LY         ; Save LY register
         LD     LY,BTOAT   ; Point to subtraction table
NUMLP    LD     A,NUMBA     ; Get ASCII 0 in A
         LD     E,(LY+0)   ;
         LD     D,(LY+1)   ; Get table value
SUBBA    OR     A           ; Clear carry bit
         SBC    HL,DE      ; Subtract table value from value
         ; input
         JP     C,GONEN    ; If carry then do for next digit
         INC    A           ; Inc count (ASCII in A)
         JR     SUBBA      ; Do next subtraction
GONEN    ADD    HL,DE       ; Restore value before last
         ; subtraction
         LD     (IX+0),A    ; Store ASCII Number in memory
         INC    IX         ; Inc memory pointer
         INC    LY         ; Point to next table value
         INC    LY         ;
         DEC    E           ; Test if E = 0
         JR     NZ,NUMLP   ; No then try for next digit
         XOR    A           ; Clear A and place in store
         LD     (IX+0),A    ; as EOS = End of string
         POP    LY         ; *
         POP    IX         ; *
         POP    DE         ; *   Restore all saved registers
         POP    HL         ; * and
         POP    AF         ; *
         RET          ; Exit

```





## CLEARING AND RESETTING ROUTINES

; CLRMF clears the MOTBF array

```

CLRMF    PUSH    BC           ; *
         PUSH    DE           ; * Save Registers used
         POP     HL           ; *
         LD     HL,MOTBF      ; Point to MOTBF(0)
         LD     DE,MOTBF +1   ; Point to MOTBF(1)
         LD     BC,5          ; BC = Count
         LD     (HL),0        ; MOTBF (0) = 0
         LDIR                    ; Copy through complete array
         POP     HL           ; *
         POP     DE           ; * Restore Registers used
         POP     BC           ; *
         RET                    ; Exit

```

; CTBUF clears TBUF, DRBUF and MOTBF  
; Note all must be in order

```

CTBUF    PUSH    BC           ; *
         PUSH    DE           ; * Save Registers
         PUSH    HL           ; *
         LD     HL,TBUF       ; HL points to TBUF(0)
         LD     DE,TBUF + 1   ; DE points to TBUF(1)
         LD     BC,17         ; BC = Count of 17
         LD     (HL),0        ; Clear first element
         LDIR                    ; Now clear next 17 elements
         POP     HL           ; *
         POP     DE           ; * Restore Registers
         POP     BC           ; *
         RET                    ; Exit

```

SUBROUTINE GINT

; This subroutine gets a signed 16 bit integer  
 ; from the TRS80 Keyboard.  
 ; If a bad number is typed it returns with the  
 ; Status flag - non zero.  
 ; The 2's complement number is returned in HL

```

GINT      PUSH    BC      ; *
          PUSH    DE      ; * Save Registers
          XOR     A        ; Clear A and carry
          SBC    HL,HL     ; Zero HL
          LD     B,5       ; Maximum of 5 characters
          LD     (MIN),A   ; Clear MIN=Minus Flag
GINT1     CALL   GCHRA    ; Get a character and display it
          CP     SPAC     ; Is it a space?
          JR     Z,GINT1   ; Yes then skip
          CP     NL       ; Is it a newline?
          JP     Z,PRET1   ; Done if new line, return zero
          CP     MINUS    ; A minus number?
          JF     NZ,POSON  ; No then see if positive
          LD     A,1      ; Set minus flag
          LD     (MIN),A   ;
          JR     GINT2    ; Get rest of number
PCSON     CP     '+'      ; Is number a positive number
          JR     NZ,NUM1   ; See if numeric
GINT2     CALL   GCHRA    ; Get next character
NUM1      CP     NL       ; Newline?
          JR     Z,NUMET   ; Yes then exit
          ADD    HL,HL     ; Double number
          PUSH   HL       ; Save X 2
          ADD    PL,HL     ; X 4
          ADD    HL,HL     ; X 8
          POP    DE       ; Restore X 2
          ADD    HL,DE     ; Now add to get X 10
          CP     0        ;
          JR     C,EFRN2   ; If number less than ASCII 0 ERR
          CP     '9' + 1  ; If number greater than ASCII
          JR     NC,EFRN2  ; 9 then error
          SUB    NUMBA    ; Number input OK, so make into
          LD     E,A      ; Binary and
          LD     D,0      ; load into DE
          ADD    HL,DE     ; Now add to total
          DJNZ  GINT2     ; Do for next digit
          CALL  PNEWL     ; Print a new line
NUMET     LD     A,(MIN)  ; Is number negative?
          OR     A        ;
          JR     Z,PRET1   ; No then finish off
          LD     A,L      ; else complement
          CPL     ; The value in HL
          LD     L,A      ;
          LD     A,H      ; (2's Complement)
  
```

```

CPL                ;
LD      H,A        ;
INC     HL         ;
PRET1   XOR     A   ; Clear A and flags
        PCP     DE ; * Restore Registers
        POP     BC ; *
        RET                    ; and return
ERRN2   CALL    PNEWL ; Print a newline
        LD     A,1 ; Set A to 1
        OR     A   ; Clear carry flag
        SBC    HL,HL ; Clear HL
        OR     A   ; Clear carry flag
        JR     PRET2 ; Return with ERROR CODE

```



SUBFOUNTINE POSDS

; This routine displays the POSAR array for the  
 ; user to see how far the arm is from its  
 ; "Home position"

```

POSDS      PUSH      AF          ; *
           FUSH      BC          ; *
           PUSH      DE          ; *   Save all registers
           PUSH      HL          ; *
           LD        HL,POSST    ; Print "RELPCS="
           CALL      PSTR        ; String
           LD        B,6         ; Motor count into B
NPCSA      LD        DE,POSAR    ; Point to array containing offsets
           LD        A,(DE)      ; Get lower order byte into
           LD        L,A         ; L
           INC       DE          ; Increment memory pointer
           LD        A,(DE)      ; Get higher order byte into
           LD        H,A         ; H
           INC       DE          ; Increment to next number
           LD        IX,NUMAR    ; IX points to result string
           CALL      CBTAS       ; Convert HL and leave in (IX)
           LI       HL,NUMAR    ; Point to result string
           CALL      PSTR        ; Print it
           CALL      PSPAC       ; Print a space
           DJNZ     NPCSA       ; Do for next motor
           CALL      PNEWL       ; Print a new line, all done
           POP       HL          ; *
           POP       DE          ; *
           POP       BC          ; *   Restore all Registers
           POP       AF          ; *
           RET                ; Now return
  
```

SUBROUTINE PCSIC

; PCSIC increments the signed 2's complement 16 bit  
 ; motor step offset counts. It does not check for overflow,  
 ; but this is very unlikely. The base would need to  
 ; be rotated about 2<sup>0</sup> times to cause such an event.

```

PCSIC      PUSH    AF          ; *
           PUSH    BC          ; *
           PUSH    DE          ; *   Save registers
           PUSH    HL          ; *
           LD      B,6         ; B = motor count
           LD      DE,MOTBF+5 ; Point to MOTBF
           LD      HL,POSAR+10; Point to POSAR (relative position)
NPOS1     FUSH    BC          ; Save motor count
           LD      C,(HL)      ; Get lower PCSAE byte in C
           INC     HL          ; Point to Higher byte
           LD      B,(HL)      ; Get higher byte in B
           LD      A,(DE)      ; Get direction byte from MOTBF
           AND     3           ; Clear all higher bits from D7-D3
           OR      A           ; Is it zero?
           JR      NZ,NONZM    ; No skip
           DEC     HL          ; Yes then move POSAR pointer back
           JR      NPOS2      ; and continue with next motor
NCNZM     BIT     1,A         ; Test direction bit
           JR      NZ,RDPOS    ; Do for reverse direction
           INC     BC          ; Advance element
           JR      STPCS      ; Restore 16 bit POSAR element
RDPOS     DEC     BC          ; Advance negative POSAR element
STPOS     LD      (HL),B      ; Store higher byte
           DEC     HL          ; Move pointer to lower byte
           LD      (HL),C      ; Store lower byte
NPOS2     DEC     HL          ; Back up PCSAR pointer to
           DEC     HL          ; next motor position slot
           DEC     DE          ; Backup MOTBF pointer to next slot
           POP     BC          ; Restore Motor count
           DJNZ   NPOS1      ; Do next motor
           POP     HL          ; *
           POP     DE          ; *   Restore used Registers
           POP     BC          ; *
           POP     AF          ; *
           RET                ; Done, Exit
  
```



SUBROUTINE STORE

; STORE copies the TBUF array into the locations pointed to  
 ; by CURCW. If the TBUF array is completely empty then the  
 ; copy is not done. The COUNT and the CUROW variables  
 ; are both updated, and a check is made to ensure that  
 ; a store overflow is caught and the user told.

```

STORE    PUSH    BC      ; *
         PUSH    HL      ; * Save registers
         LD     HL,TBUF  ; Point to TBUF
         LD     B,6     ; B = motor count
STEST    LD     A,(HL)   ; Get TBUF (N)
         OR     A       ; Is TBUF element zero
         JR     NZ,STOR1 ; No then do store
         INC    HL      ; Point to next element
         DJNZ  STEST    ; Go do next element check
         JR     EXIT    ; All TBUF zero so exit
STOR1    LD     (1X+0),0 ; Clear DRBUF element
         LD     HL,(COUNT) ; Get current count value
         INC    HL      ; Advance it
         LD     A,H     ; See if cver or at 512 bytes
         CP     1       ;
         JP     NC,OVRFW ; Yes then overflow
         LD     (COUNT),HL ; Put back advanced count
         LD     DE,(CUROW) ; Get current row pointer in DE
         LD     HL,TBUF ; Get TBUF pointer in HL
         LD     BC,0006 ; Count for six motors
         LDIR    ; Copy TBUF to ARST(1)
         LD     (CUROW),DE ; Replace updated rcw pointer CURCW
EXIT     CALL    CTBUF   ; Clear buffers
         POP    HL      ; *
         POP    BC      ; * Restore Registers
OVRFW    RET        ; Now return to caller
         LD     HL,OVRMS ; Print overflow situation
         CALL   PSTR    ; Message
         CALL   GCHRA   ; Get response
         CALL   PNEWL   ; Print a new line
         CP     'D'    ; User typed a 'D'
         JP     Z,REDO  ; Yes then clear all
         CP     'S'    ; User typed an 'S'
         JR     Z,EXIT2 ; Yes exit with sequence saved
         JR     OVRFW   ; Bad input, try again
REDO     CALL    JNIT    ; Clear all arrays etc
EXIT2    POP    HL      ; *
         POP    BC      ; * Restore Registers
         POP    BC      ; Throw away return address
         JP     QUES1   ; Back to main loop
  
```



SUBROUTINE RESET

; This subroutine clears the POSAR array

```
RESET    PUSH    BC          ; *
         PUSH    DE          ; * Save Registers
         PUSH    HL          ; *
         LD     HL,POSAR     ; Point to POSAR start
         LD     DE,POSAR+1   ; Point to next element
         LD     (HL),00      ; Clear first POSAR element
         LE     BC,11        ; Eleven more row counts to clear
         LDIR                    ; Clear POSAR array
         LD     HL,STRST     ; Print "ARM RESET" message
         CALL  PSTR          ; and
         POP    HL           ; *
         POP    DE           ; * Restore Registers and
         POP    BC           ; *
         RET                    ; Return to caller
```

## INPUT/OUTPUT ROUTINES

; PUTCHR prints a character in A

```

PUTCHR      PUSH   AF      ; Save AF
            PUSH   DE      ; Save DE
            CALL  PCHR    ; Print character in A
            POP    DE      ; Restore DE
            POP    AF      ; Restore AF
            RET                    ; Done, Exit
    
```

; PSTR prints a string pointed to by HL

```

PSTR       PUSH   BC      ; * Save registers that are
            PUSH   DE      ; * corrupted by the TRS80
            CALL  PUTSTR  ; Print the string
            POP    DE      ; * Restore Registers
            POP    BC      ;
            RET                    ; Done, Exit
    
```

: PSPAC prints a space character

```

PSPAC      PUSH   AF      ; Save AF
            LD     A,20    ; A = Space character
            CALL  PUTCHR  ; Print it
            POP    AF      ; Restore AF
            RET                    ; Done, Exit
    
```

; PNEWL prints a new line to the screen

```

PNEWL     PUSH   AF      ; Save AF
            LD     A,0DH   ; A = Newline character
            CALL  PUTCHR  ; Print it
            POP    AF      ; Restore AF
            RET                    ; Done, Exit
    
```

: SCKBD Scans the keyboard once and returns, non  
; zero if character found

```

SCKBD     PUSH   DE      ; Save DE
            CALL  KBI     ; See if character is there
            POP    DE      ; Restore
            RET                    ; Done, Exit
    
```

; GCHRA gets a character from keyboard and displays it

```

GCHRA     CALL  GCHR    ; Get a character
            CALL  PUTCHR  ; Print it
            RET                    ; Done, Exit
    
```

CLEAR SCREEN ROUTINE

; Simple scrolling type screen clear

CLRSC	PUSH	BC	; Save used register
	LD	B,16	; Get screen row count
UPLRW	CALL	PNEWL	; Print a new line
	DJNZ	UPLRW	; Do 16 times
	POP	BC	; Restore Register
	RET		; Exit



DELAY ROUTINES

```

DELSW      PUSH      BC      ; Delay for 10 * E + 10 M cycles
DELS1      PUSH      BC      ; Save BC
           NOP        ; Delay for 11 T state
           NOP        ; 4 T state delay
           POP        ; 4 T state delay
           DJNZ      DELS1    ; Delay for 11 T states
           POP        ; Do delay times value in B
           RET        ; Restore BC
           RET        ; Exit
DELS       PUSH      BC      ; Save BC
           LD        B,20     ; Set B for 0.001 sec delay (apx)
           CALL     DELSW    ; Do delay
           POP        ; Restore EC
           RET        ; Exit
DELT       PUSH      BC      ; Save BC
           LD        E,0      ; Set B for 0.01 sec delay (apx)
           CALL     DELSW    ; Do delay
           POP        ; Restore BC
           RET        ; Exit
DELLN      PUSH      EC      ; Save BC
           LD        B,200    ; Set B for 1.0 sec delay (apx)
DELD       CALL     DELSW    ; Do delay
           DJNZ      DELD     ; Do next delay section
           POP        ; Restore BC
           RET        ; Exit

```

FULL STEPPING AND HALF STEPPING THE MOTORS

Two tables are shown below, the first indicates the sequence for full stepping the motors and the second table shows the pulse pattern for half stepping the motors.

FULL STEPPING SEQUENCE

<u>QA</u>	<u>QB</u>	<u>QC</u>	<u>QD</u>	<u>STEP</u>
1	∅	1	∅	1
1	∅	∅	1	2
∅	1	∅	1	3
∅	1	1	∅	4

HALF STEPPING PULSE SEQUENCE

<u>QA</u>	<u>QB</u>	<u>QC</u>	<u>QD</u>	<u>STEP</u>
1	∅	1	∅	1
1	∅	∅	∅	1.5
1	∅	∅	1	2
∅	∅	∅	1	2.5
∅	1	∅	1	3.∅
∅	1	∅	∅	3.5
∅	1	1	∅	4
∅	∅	1	∅	4.5

The documental program contains a table FTABL which is shown below. This table contains the step sequence for full stepping also shown below is the new table FTABLH which contains the sequence for half stepping. To use this table (FTABLH) in the program it will be necessary to alter a few lines of code in the DRAMT routine. The comparison with 5 CPI 5 should be changed to a comparison with 9 and the program line LD A,4 should be changed to LD A,8. The table FTABL should now be changed so it appears as FTABLH

FULL STEP TABLE

			Step number
FTABL	DEFB	192	1
	DEFB	144	2
	DEFB	48	3
	DEFB	96	4

HALF STEP TABLE

			Step number
FTABLH	DEFB	192	1
	DEFB	128	1.5
	DEFB	144	2
	DEFB	16	2.5
	DEFB	48	3
	DEFB	32	3.5
	DEFB	96	4
	DEFB	64	4.5

If you compare the table values with the tables on the previous page you will note a difference, this is because QB and QC are exchanged in the above table due to the hardware switching these two lines.

NOTE

REMEMBER WHEN WRITING PROGRAMS DIRECTLY DRIVE THE ARM SO THAT THE QB AND QC OUTPUT BITS SHOULD BE REVERSED, SO THAT THE TOP FOUR BITS ARE:-

D8 = QA  
D7 = QC  
D6 = QB  
D5 = QD



A

P

P

L

I

C

A

T

I

O

N

S

#### CONSTRUCTION OF A SUITABLE PORT FOR THE ARMDROID

A circuit diagram is given which describes in particular the construction of an 8 bit bi-directional, non latched port. The circuit as given is for the TRS80 bus, but it should be possible with reasonably simple modifications to alter it for most Z80 type systems.

The circuit described is a non latched port so the output data will appear for only a short period on the 8 data lines.


As can be seen from the diagram, the circuit draws its 5 volt power supply from the arm's interface port, and not from the processor it is connected to. The port was constructed this way due to the fact that some commercial microprocessor systems do not have a 5v output supply.

When the above circuit is connected to the arm's interface card the bottom bit is usually pulled high, thus if the user inputs from the port at any time the data presented will mirror the state of the reed switches.

To output data to the arm using this port the user should send the data to the port with the bottom bit cleared. The data will then be latched through to the addressed arm motor latch.

The components for the described port should be easily available from most sources.

TRS80 8 BIT INTERFACE (NON LATCHED BI-DIRECTIONAL)



IC 1: 74LS27  
IC 2: 74LS20  
IC 3: 74LS00  
IC 4: 74LS245

Pin 14: 5 Volts, Pin 7: GND  
Pin 14: 5 Volts, Pin 7: GND  
Pin 14: 5 Volts, Pin 7: GND  
Pin 20: 5 Volts, Pin 10: GND

3\*3 INPUT NOR  
2\*4 INPUT NAND  
4\*2 INPUT NAND  
OCTAL BUS TRANSCEIVER (Tri-state)



CONNECTION OF ARMDROID TO PET/VIC COMPUTERS

PET/VIC USER PORT CONNECTOR

PIN NO	PET/VIC NOTATION	ARMDROID NOTATION
C	PA0	D1
D	PA1	D2
E	PA2	D3
F	PA3	D4
H	PA4	D5
J	PA5	D6
K	PA6	D7
L	PA7	D8
N	GROUND	GROUND

I/O Register Addresses (User Ports)

VIA Data Direction Control: 37138

PET Data Directional Control Register: 59459

VIC I/O Register Address: 37136

PET Data Register Address: 59471

The data direction registers in the VIA define which bits on the respective user ports are input and which are to be used as output bits. A binary one in any bit position defines an output bit position and a zero defines that bit as an input bit.

SIMPLE BASIC ARM DRIVER FOR VIA (PET/VIC)

```
5 L = 37136: Q = 37138
10 PRINT "VIC ARMDROID TEST"
20 PRINT
30 PRINT "HALF STEP VALUES"
40 T = 8: C = 2: S = 10: M = 1: I = 1: A$ = "F"
50 FOR I = 1 TO T: READ W(I): PRINT W(I): NEXT I
60 POKE Q, 255
70 INPUT "MOTOR NUMBER (1-6)"; M
80 IF M < 1 OR M > 6 THEN 70
90 INPUT "FORWARD BACKWARD"; A$
100 IF A$ = "F" THEN D = 0: GOTO 130
110 IF A$ = "B" THEN D = 1: GOTO 130
120 GOTO 90
130 INPUT "STEPS"; S
140 IF S < 1 THEN 130
150 O = M + M + 1
160 FOR Y = 1 TO S * C
170 F = W(I) + O
180 POKE L, F
190 POKE L, F - 1
200 IF D = 0 THEN 230
210 I = I + 1: IF I > T THEN I = 1
220 GOTO 240
230 I = I - 1: IF I < 1 THEN I = T
240 NEXT Y
250 GOTO 70
260 DATA 192, 128, 144, 16, 48, 32, 96, 64
```

THE VALVES FOR L AND Q FOR THE PET ARE

Q = 59459 = DATA DIRECTION  
L = 59471 = I/O

## MOTOR STEP RELATIONSHIP PER DEGREE INCREMENT

Below are shown the calculations for each joint to enable the user to calculate the per motor step relationship to actual degree of movement.

These constants will necessary for users wishing to formulate a cartesian frame reference system or a joint related angle reference system.

### Base

Motor step angle x ratio 1 x ratio 2

$$7.5^{\circ} \times \frac{20 \text{ teeth}}{72 \text{ teeth}} \times \frac{12 \text{ teeth}}{108 \text{ teeth}}$$

=  $\emptyset.2314$  degree step or 4.32152 steps per degree.

### Shoulder

$$7.5 \times \frac{14 \text{ teeth}}{72 \text{ teeth}} \times \frac{12 \text{ teeth}}{108 \text{ teeth}}$$

=  $\emptyset.162$  degree per step or 6.17284 steps per degree

### Elbow

Same as shoulder joint

### Wrists

Same as base joint calculations

### Hand

$$7.5 \times \frac{20 \text{ teeth}}{72 \text{ teeth}} \times \frac{12 \text{ teeth}}{108 \text{ teeth}} = \emptyset.231 \text{ degree per step}$$

$$\frac{\pi \times d \times .231}{360} = (\emptyset.0524/2) \text{ mm}$$

=  $\emptyset.0262$  mm = hand pulley motion per step

Total hand open to close pulley movement =  $2\emptyset.0$  mm

Angle traversed by single finger =  $5\emptyset^{\circ}$

$$\frac{5\emptyset^{\circ}}{2\emptyset.0 \text{ mm}} \times \emptyset.0262 \text{ mm}$$

=  $\emptyset.0655^{\circ}$  per step or 15.2672 step per degree

$$\pi = 3.1415926$$

d = 26mm = pulley diameter



SOME OVERALL DIMENSIONS

Shoulder pivot to pivot = 190mm  
Forearm pivot to pivot = 190mm  
Finger wrist pivot to fingers closed = 90mm  
wrist pivot to finger open (90) = 99mm  
Bottom of base to shoulder pivot = 238mm

ANGULAR JOINT SPANS

Shoulder up = 153 ,down 45  
Forearm up = 45 ,down 150  
Wrist up = 100 ,down 100  
Base no limit ,but suggest caution not to  
overwind cables in base  
Hand fingers move over 50

(All above measurements are in degrees)

NOTE

The above measurements were taken with the arm joints held in a horizontal plane.




SOME EXTRA POINTS TO BEAR IN MIND

- a) Long Lead of LED goes to NEGATIVE  
Short lead of LED goes via 4.7 kohm Resistor  
to POSITIVE
  
- b) Due to LED hole being slightly too large a grommet  
will first have to be fitted to the LED and its holder  
can then be super glued if necessary into the grommet.
  
- c) The Torque available is largely a function of speed  
and hence the user can expect performance to deteriorate  
as speed is increased. Tables are supplied earlier  
in the manual.

FINAL NOTE

BEST WISHES AND GOOD LUCK

*D. R. K. R.*




METAL WASHERS (FOR SPACING) INDIVIDUAL THICKNESS = 1



DRAWING NUMBER  
A2 / 1

BILL OF MATERIAL


NO. OF ITEMS MAT'L DESCRIPTION REMARKS



A2/RB1 / 5

AUTH. NO. ....		DESIGNED .....	PRINT ISSUED .....
PROJECT NO. ....		DRAWN .....	DATE .....
WORK ORDER NO. ....		CHECKED .....	DEPARTMENT .....
SCALE .....		APPROVED .....	DRAWING NUMBER
REFERENCE DRAWING		APPROVED .....	A2/RB1/5
NO.	DATE	DESCRIPTION	REVISIONS
		MADE BY	CHECKED BY

DRAWING NUMBER  
A2 /



A2/RB1 / 4

BILL OF MATERIAL		REMARKS
NO OF ITEMS	DESCRIPTION	

AUTH. NO. ....		DESIGNED .....	PRINT .....
PROJECT NO. ....		DRAWN .....	ISSUED .....
WORK ORDER NO. ....		CHECKED .....	DATE .....
SCALE .....		APPROVED .....	DRAWN .....
REFERENCE DRAWING		APPROVED .....	DRAWING NUMBER
REVISIONS		A2/RB1 / 4	
NO.	DATE	DESCRIPTION	MADE BY
			CHECKED BY


DEPARTMENT  
**COLNE ROBOTICS**



DRAWING NUMBER  
A2/1

BILL OF MATERIAL

NO OF P	ITEM	MAT	L	DESCRIPTION	REMARKS
---------	------	-----	---	-------------	---------




AUTH. NO. ....		DESIGNED .....		PRINT ISSUED .....	
PROJECT NO. ....		DRAWN .....		DATE .....	
WORK ORDER NO. ....		CHECKED .....		DRAWN .....	
SCALE .....		APPROVED .....		DRAWING NUMBER	
REFERENCE DRAWING		APPROVED .....		A2/RB1/2	
NO		DATE		DEPARTMENT	
DESCRIPTION		MADE BY		COLNE ROBOTICS	
REVISIONS		CHECKED BY			





DRAWING NUMBER  
A2/ /

BILL OF MATERIAL  
DESCRIPTION  
REMARKS



A2/RB1 / 3

- 30
- 118
- 31
- 123
- 116
- 38
- 110
- 37
- 107
- 36
- 130
- 35
- 117
- 122
- 29
- 111
- 21
- 108
- 107
- 112
- 24
- 26

- 121
- 109
- 33
- 109
- 112
- 32
- 133
- 34
- 131
- 55
- 54
- 102
- 53
- 102

- 108
- 111
- 122
- 117

REVISIONS		REFERENCE DRAWING	
NO.	DATE	DESCRIPTION	MADE BY / CHECKED BY


  

AUTH. No. ....	DESIGNED .....
PROJECT No. ....	DRAWN .....
WORK ORDER No. ....	CHECKED .....
SCALE .....	APPROVED .....
	APPROVED .....

DEPARTMENT	PRINT
<b>COLNE ROBOTICS</b>	ISSUED .....
	DATE .....
	DRAWN .....
DRAWING NUMBER	DRAWING NUMBER
<b>A2/RB1/3</b>	<b>A2/RB1/3</b>

**INTERFACE BOARD OVERLAY**



- IC 1-2 : 74LS125
- IC 3 : 74LS04
- IC 4 : 74LS123
- IC 5 : 74LS366
- IC 6 : 74LS138
- IC 7-12 : 74LS175
- IC 13-16 : ULN2003A
- R 1 - 1K
- R 2 & 13 - 10K
- R 3-8 - 2K2
- R 9-11 - 1K8
- R 12 - 15K
- R 14 - 18 oh 5W
- C 1 - 100pF
- C 2 - 1µF
- C 3 - 10nF
- C 4-15 - 10nF
- ZD 1 - 13V
- IC 17 : UA7805

NOTE  
 IC5 used only with reed switches : SW  
 ○ thru pins

**COLNE ROBOTICS CO. LTD.**